

Ford



## General information

Make	FORD
Model	C-MAX TITANIUM
Colour	Grey
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J







# Internet history

Entry 2	
Date	2021-12-21
Pictures	15
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-11-02
Pictures	10
Listing price	View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-04
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #15	2024-01-02 13:19
MOT test number	601343017715
Result	✓ Passed
Next expiry date	2025-01-04

MOT #14	2022-12-08 17:21
MOT test number	977418215158
Result	✓ Passed

MOT #13	2022-12-08 15:34	
MOT test number	821896524878	
Result	× Failed	
<b>MAJOR</b> Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))		
<b>MAJOR</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
<b>DANGEROUS</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Central Play in steering rack inner joint(s)		
<b>Pass with rectification</b> Nearside Stop lamp(s) not working (4.3.1 (a) (ii))		
<b>MAJOR</b> Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))		
<b>DANGEROUS</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		





MOT #12		2021-12-20 17:21
MOT test	number	267067804846
Result		✓ Passed
Advice	Offside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Offside Front Lower Windscreen damaged but not adversely affecting driver's vie	w (3.2 (a) (i))

MOT #11	2021-01-05 10:14
MOT test number	191472294995
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10		2019-09-18 14:25
MOT test	number	193528268071
Result		✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #9	2018-08-25 09:39
MOT test number	558447301519
Result	✓ Passed

MOT #8	2018-04-20 13:53
MOT test number	238226884432
Result	✓ Passed



YS59LCU
report date: 2024-03-29

MOT #7	2018-04-17 11:13
MOT test number	322181470729
Result	🗙 Failed
Advice Rear brake pads worn low.	
<b>Fail</b> Offside Inner Front constant velocity joint gaiter damaged to the extent that ingress of dirt etc (2.5.C.1a)	it no longer prevents the
Advice Auxiliary drive belt noisy.	
Advice Slight play rear anti roll bar links and D bushes.	
FailNearside Headlamp not working on dipped beam (1.7.5a)	
<b>Fail</b> Offside Rear Tyre has ply or cords exposed Inner shoulder of tread worn very small cuts to expose cords. (4.1.D.1b)	thin and has numerous

MOT #6		2017-04-25 14:56
MOT test	number	182355195230
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit tyre perished (4.1.E.1)	

MOT #5	2016-04-21 14:27
MOT test number	491649266878
Result	✓ Passed
Advice Offside Front worn on inner edge	

MOT #4	2015-04-17 13:00
MOT test number	855457005111
Result	✓ Passed





MOT #3	2015-04-17 10:28
MOT test number	276667605128
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
MOT #2	2014-02-01 11:06
MOT test number	617362034080
Result	✓ Passed
MOT #1	2013-01-25 09:35
MOT test number	356755723083
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 July 2024	4 January 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-22
Last registration	2024-01-02
Complete history	See info



Registration #1	2010-02-22	9 mi
Registration #2	2013-01-25	22.815 mi
Registration #3	2014-02-01	28.260 mi
Registration #4	2015-04-17	37.208 mi
Registration #5	2015-04-17	37.211 mi
Registration #6	2016-04-21	42.805 mi
Registration #7	2017-04-25	47.670 mi
Registration #8	2018-04-17	53.445 mi
Registration #9	2018-04-20	53.453 mi
Registration #10		11.777 est
Registration #11		11.707 est
Registration #12		11.777 est
Registration #13		11.707 est
Registration #14		11.777 est
Registration #15		11.707 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.117 est





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AU29117