





## General information

Make	PEUGEOT
Model	206 LOOK
Colour	Silver
Year of manufacture	2008
Top speed	106 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	74 BHP	0 < 101 A
Max. torque	120 Nm at 3.400 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.360 cc	121 - 140
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185 H
Consumption city	31.7 mpg	186 - 225 J
Consumption extra urban	56.5 mpg	225+
Consumption combined	44.1 mpg	
CO2 emission	152 g/km	
CO2 label	G	





### Internet history

Entry 1

Date Pictures 2021-12-15

12

Listing price

View report









source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	33
Total items failed	2

MOT #18		2023-12-20 09:56
MOT test	number	690905974559
Result		✓ Passed
Next exp	iry date	2024-12-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Subframe mounting prescribed area is corroded but not considered ex	xcessive (5.3.6 (a) (i))
Advice	Front Coil spring corroded Both (5.3.1 (b) (i))	
Advice	Registration plate deteriorated but not likely to be misread Both (0.1 (b))	
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	



SPO8NZD report date: 2024-03-28

MOT #17		2023-12-09 10:33
MOT test	number	863290341763
Result		🗙 Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Subframe mounting prescribed area is corroded but not considered exces	ssive (5.3.6 (a) (i))
Advice	Front Coil spring corroded Both (5.3.1 (b) (i))	
<b>Minor</b> (4.7.1 (b)	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (i))	or light sources
Advice	Registration plate deteriorated but not likely to be misread Both $(0.1 (b))$	
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
<b>MAJOR</b> (g) (ii))	Front Steering rack gaiter missing or no longer prevents the ingress of dirt Bot	h sides loose (2.1.3

MOT #16		2022-12-17 10:45
MOT test	number	568651083945
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Minor</b> (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or lig	tht sources (4.7.1
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #15	2021-12-17 15:18
MOT test number	271940403530
Result	✓ Passed



SPO8NZD report date: 2024-03-28

MOT #14		2021-03-24 09:20
MOT test	number	902018236481
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Play in steering rack inner joint(s)	

MOT #13	2020-03-21 12:17
MOT test number	687183875456
Result	✓ Passed

MOT #12		2020-03-21 10:26
MOT test	number	659867903081
Result		🗙 Failed
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #11	2019-03-06 17:04
MOT test number	343632302488
Result	✓ Passed

MOT #10	2019-03-06 12:30
MOT test number	757208967652
Result	🗙 Failed
<b>DANGEROUS</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	





MOT #9 2018-03-26 13:26 **MOT test number** 443337819992 Result ✓ Passed 2018-03-21 11:43 MOT #8 742054492647 **MOT test number** × Failed Result Fail Offside Front Steering pivot point has excessive play (2.2.B.1g) Fail Supplementary Restraint System warning lamp indicates a fault air bag (5.4.2)

MOT #7		2017-03-17 09:27
MOT test	number	732156497761
Result		✓ Passed
Advice	Offside Play in steering rack inner joint(s)	
Advice	Front brake pads appear to be worn low.	
Advice	O/s headlight has a broken mount but is still held secure.	

МОТ #6	2016-03-04 10:02
MOT test number	146736897359
Result	✓ Passed
Advice Slight play, o/s steering.	

MOT #5		2015-03-19 12:46
MOT test	number	456118375017
Result		✓ Passed
Notice	Advise spare wheel carrier slightly loose	
Notice	Advise rear exh box heavily corroded	





MOT #4	2014-03-11 09:41
MOT test number	507970874094
Result	✓ Passed
MOT #3	2013-03-12 09:45
MOT test number	606961473086
Result	✓ Passed
MOT #2	2012-03-08 08:47
MOT test number	555928962092
Result	✓ Passed
MOT #1	2011-03-28 13:48
MOT test number	127327681467
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 4 April 2024	✓ MOT Expires: 19 December 2024
Tax status	Expired at 4 April 2024
Days left	25 days too late
MOT expiry date	19 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PANAL
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	ant
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SPO8NZD report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-31
Last registration	2023-12-20
Complete history	See info



Registration #1	2008-03-31	12 mi
Registration #2	2011-03-28	5.148 mi
Registration #3	2012-03-08	7.071 mi
Registration #4	2013-03-12	8.125 mi
Registration #5	2014-03-11	8.847 mi
Registration #6	2015-03-19	13.955 mi
Registration #7	2016-03-04	22.825 mi
Registration #8	2017-03-17	29.528 mi
Registration #9	2018-03-21	36.582 mi
Registration #10	2018-03-26	36.703 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.117 mi
Registration #19		11.777 mi
Registration #19 Registration #20		00.000 est







### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg
Additional information	
Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	FST65847856