



report date: 2024-03-29

General information

Make	KIA
Model	VENGA CRDI 2 ECODYNAMICS
Colour	Red
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 3


Date	2021-09-01
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-08-31
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	5

MOT #15	2023-05-22 13:47
MOT test number	771977992477
Result	✓ Passed
Next expiry date	2024-05-21
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #14**

2023-05-10 13:37

MOT test number

706616155874

Result

✗ Failed

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #13**

2022-07-25 10:05

MOT test number

390815956806

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened pitted on inside edge (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened pitted on inside edge (1.1.14 (a) (ii))**MOT #12**

2021-07-27 10:28

MOT test number

225211801376

Result

✓ Passed



MOT #11	2021-07-17 10:24
MOT test number	404498040797
Result	✗ Failed
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-03-03 16:26
MOT test number	841740801632
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9	2019-03-07 15:17
MOT test number	987988120611
Result	✓ Passed

MOT #8	2018-03-21 12:50
MOT test number	674350476374
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2018-03-13 10:21
MOT test number	444859042905
Result	✗ Failed
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-03-10 15:28**MOT test number** 679809978935**Result** ✓ Passed**MOT #5** 2017-03-08 16:38**MOT test number** 933438382373**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #4** 2016-03-02 11:05**MOT test number** 265847626288**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-03-20 12:29**MOT test number** 846949975036**Result** ✓ Passed**MOT #2** 2014-03-21 12:27**MOT test number** 457970384045**Result** ✓ Passed**MOT #1** 2013-03-12 14:18**MOT test number** 219681973097**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
21 May 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	21 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YH10CYZ
Plate since	2019-03-29
Current registration	YH10CYZ
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-31
Last registration	2023-05-22
Complete history	See info



Registration #1	2010-03-31	9 mi
Registration #2	2013-03-12	21.351 mi
Registration #3	2014-03-21	27.040 mi
Registration #4	2015-03-20	33.668 mi
Registration #5	2016-03-02	40.728 mi
Registration #6	2017-03-08	45.896 mi
Registration #7	2017-03-10	45.896 mi
Registration #8	2018-03-13	50.372 mi
Registration #9	2018-03-21	50.395 mi
Registration #10	2019-03-07	54.814 mi
Registration #11	2019-03-20	55.377 mi
Registration #12	2019-03-20	55.377 mi
Registration #13	2019-03-20	55.377 mi
Registration #14	2019-03-20	55.377 mi
Registration #15	2019-03-20	55.377 mi
Registration #16	2019-03-20	55.377 mi
Registration #17	2019-03-20	55.377 mi
Registration #18	2019-03-20	55.377 mi
Registration #19	2019-03-20	55.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	66%
Pedestrian	64%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FCAZ005578