





General information

Make	KIA
Model	CEED CRDI 2 ECODYNAMICS
Colour	Silver
Year of manufacture	2015
Top speed	122 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	А





MOT history

MOT expiry date	2024-10-16
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	7
Total items failed	11

MOT #10	2023-10-17 10:24
MOT test number	317914947942
Result	✓ Passed
Next expiry date	2024-10-16

MOT #9)	2023-10-09 14:03	
MOT te	st number	805029184801	
Result		🗙 Failed	
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))		
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))		
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))		

MOT #8	2022-10-10 16:2	7
MOT test	number 70420057046	3
Result	✓ Passe	d
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion (1.1.14 (a) (ii))	



MOT #7	2022-10-10 11:03	
MOT test number	211801288445	
Result	🗙 Failed	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion (1.1.14 (a) (ii))		
FailNearside Front Position lamp not working (4.2.1 (a) (ii))		
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Front Service brake lagging in operation (1.2.1 (d))		

МОТ #6	2021-09-01 14:51
MOT test number	784719477040
Result	✓ Passed

MOT #5	2020-08-24 15:21
MOT test number	752695535074
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #4	2020-08-24 08:09
MOT test number	784102405993
Result	🗙 Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
FailOffside Position lamp not working (4.2.1 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk

MH15GOP

report date: 2024-03-28



Μ		1	5	G	0	Ρ
I	repo	ort e	date	: 20	24-0	3-28

MOT #3 2019-08-28 12:32 **MOT test number** 365110339036 Result 🗸 Passed 2019-08-23 14:21 MOT #2 **MOT test number** 200321147691 Result × Failed Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #1	2018-08-29 14:47
MOT test number	984030616982
Result	✓ Passed



MH15GOP report date: 2024-03-28

Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	Expires: 16 October 2024
Tax status	Valid until 1 April
Days left	338
MOT expiry date	16 October 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PANAL
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	ant
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



MH15GOP report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-08-28
Last registration	2023-10-17
Complete history	See info



Registration #1	2015-08-28	28 mi
Registration #2	2018-08-29	25.704 mi
Registration #3	2019-08-23	36.243 mi
Registration #4	2019-08-28	36.630 mi
Registration #5	2020-08-24	48.150 mi
Registration #6	2020-08-24	48.152 mi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi



MH15GOP report date: 2024-03-28

Car features

S0225	Air conditionin
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1499 kg
Max. allowed weight	1810 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	D4FBEZ614629