



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Red
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-10
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-14
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	43
Total items failed	8

MOT #12	2023-06-26 11:14
MOT test number	501837039482
Result	✓ Passed
Next expiry date	2024-07-14
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Oil leak, but not excessive gearbox oil leak (8.4.1 (a) (i))

MOT #11	2022-07-11 08:18
MOT test number	290570812581
Result	✓ Passed

**MOT #10**

2021-07-15 18:16

MOT test number

598568302781

Result

✓ Passed

- Advice** Exhaust system corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Sump corroded
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9

2020-02-17 10:06

MOT test number

357748933881

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge at 3mm also cracking on tread and worn on edges - 195/60R15 (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Minor** Nearside Front Obligatory mirror slightly damaged mirror unit damaged and loose but not likely to fall off (3.3 (b) (i))
- Advice** Oil leak, but not excessive gearbox area (8.4.1 (a) (i))
- Advice** Sump corroded
- Advice** Offside Front Tyre worn close to legal limit/worn on edge at 3mm and worn badly on edges - 195/60R15 (5.2.3 (e))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Both front wipers slightly smearing screen
- Advice** Exhaust system corroded

**MOT #8**

2019-02-04 09:53

MOT test number

314894150713

Result

✓ Passed

Minor Offside Windscreen damaged but not adversely affecting driver's view Zone B (3.2 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases Silencer deteriorated (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2/4mm (5.2.3 (e))**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Oil leak, but not excessive Gearbox shaft seal (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2/4mm (5.2.3 (e))**MOT #7**

2019-02-03 11:51

MOT test number

226610710159

Result

✗ Failed

Advice Nearside Non obligatory mirror damaged**Advice** Rear Exhaust has a minor leak of exhaust gases Silencer deteriorated (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2/4mm (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view Zone B (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2/4mm (5.2.3 (e))**Advice** Nearside Oil leak, but not excessive Gearbox shaft seal (8.4.1 (a) (i))**MOT #6**

2018-01-17 11:31

MOT test number

989330906494

Result

✓ Passed

Advice Engine sump corroded + leaking slightly**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5**

2018-01-17 09:33

MOT test number

546139023645

Result**✗ Failed**

- Advice** Front Wiper blades worn
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Brake pad(s) wearing thin 4mm approx (3.5.1g)
- Advice** Engine sump corroded + leaking slightly
- Advice** Nearside Front Brake pad(s) wearing thin 3/4mm approx (3.5.1g)
- Fail** Rear Brakes imbalanced across an axle 46% (3.7.B.5b)

MOT #4

2017-02-17 13:56

MOT test number

519122624765

Result**✓ Passed**

- Advice** Tailgate stuck shut (plip inop)

MOT #3

2017-02-16 15:01

MOT test number

234791983176

Result**✗ Failed**

- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Front Both running lamps out
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Tailgate stuck shut (plip inop)



MOT #2	2016-03-10 08:08
MOT test number	784927241253
Result	✓ Passed

MOT #1	2016-03-08 15:51
MOT test number	464782351802
Result	✗ Failed
Fail	Offside Front Headlamp aim too high no pattern (1.8)
Fail	Nearside Front Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-29
Last registration	2023-06-26
Complete history	See info



Registration #1	2013-03-29	16 mi
Registration #2	2016-03-08	21.213 mi
Registration #3	2016-03-10	21.213 mi
Registration #4	2017-02-16	42.440 mi
Registration #5	2017-02-17	42.440 mi
Registration #6	2018-01-17	53.974 mi
Registration #7	2018-01-17	53.974 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0272619