



report date: 2024-03-28

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	White
Year of manufacture	2011
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-15
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-12
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	30
Total items failed	14

MOT #15	2023-08-08 11:04
MOT test number	390378789376
Result	✓ Passed
Next expiry date	2024-08-12
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14	2023-08-08 10:24
MOT test number	816121141126
Result	✗ Failed
Fail	Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13	2022-07-21 15:51
MOT test number	963786705250
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12**

2022-07-19 14:51

MOT test number

580786899185

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge 175/70x14 (5.2.3 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Tyre has ply or cords exposed 175/70x14 (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 175/70x14 (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11**

2021-08-10 15:15

MOT test number

969422899646

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #10**

2020-08-13 10:13

MOT test number

596719497681

Result**✓ Passed****Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #9	2019-08-06 11:38
MOT test number	775517621508
Result	✓ Passed

MOT #8	2018-09-26 11:52
MOT test number	404281849442
Result	✓ Passed

Advice Nearside Rear tyre has a cut in it but not deep enough to reach the cords

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #7	2018-09-26 11:52
MOT test number	520634785338
Result	✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear tyre has a cut in it but not deep enough to reach the cords

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))



MOT #6	2017-09-29 10:25
MOT test number	826566487068
Result	✓ Passed

MOT #5	2017-09-27 11:13
MOT test number	328718838358
Result	✗ Failed
<div><div>Fail</div> Nearside Headlamp aim too low and too far to the right. (1.8)</div> <div><div>Fail</div> Windscreen washer provides insufficient washer liquid (8.2.3)</div> <div><div>Fail</div> Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)</div> <div><div>Fail</div> Nearside Stop lamp not working (1.2.1b)</div>	

MOT #4	2016-09-14 10:32
MOT test number	688382472543
Result	✓ Passed
<div><div>Advice</div> Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)</div>	

**MOT #3** 2016-09-13 09:47**MOT test number** 501739239326**Result** ✗ Failed

- Fail** Nearside Front front brake binding (3.7.B.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2015-09-30 11:08**MOT test number** 846534341864**Result** ✓ Passed**MOT #1** 2014-11-13 15:16**MOT test number** 365837514354**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
12 August 2024

Tax status		Valid until 1 July
Days left		64
MOT expiry date		12 August 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-11-30
Last registration	2023-08-08
Complete history	See info



Registration #1	2011-11-30	24 mi
Registration #2	2014-11-13	60.427 mi
Registration #3	2015-09-30	67.069 mi
Registration #4	2016-09-13	78.286 mi
Registration #5	2016-09-14	78.286 mi
Registration #6	2017-09-27	85.717 mi
Registration #7	2017-09-29	85.718 mi
Registration #8	2018-09-26	91.717 mi
Registration #9	2018-09-26	91.717 mi
Registration #10	2019-09-26	91.717 mi
Registration #11	2019-09-26	91.717 mi
Registration #12	2019-09-26	91.717 mi
Registration #13	2019-09-26	91.717 mi
Registration #14	2019-09-26	91.717 mi
Registration #15	2019-09-26	91.717 mi
Registration #16	2019-09-26	91.717 mi
Registration #17	2019-09-26	91.717 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Wheel base	2725 mm
Kerb weight	1269 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	126365