





report date: 2024-03-28

### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Orange
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/11



### Internet history

### Entry 1

Date	2021-07-09
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2022-10-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	12
Total items failed	7

MOT #14	2021-10-11 10:36
MOT test number	636288744345
Result	✓ Passed
Next expiry date	2022-10-10

MOT #13	2020-09-29 13:33
MOT test number	674362914947
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping	g effect (5.3.2 (b))
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	

MOT #12	2019-09-23 07:39
MOT test	number 724619369940
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/11



Result

Result

**GY590XK** 

report date: 2024-03-28

× Failed

Passed

**MOT #11** 2018-10-10 14:57

**MOT** test number 628346210271

Result ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-10-09 15:42

**MOT** test number 896298102221

Fail

Reversing lamp inoperative (4.6.1 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT** #9 2017-10-03 13:58

197340701176 **MOT** test number

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2016-10-07 12:31

**MOT** test number 253912971465

Result Passed

**MOT #7** 2016-10-07 12:31

**MOT** test number 282910657871

× Failed Result

**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/11



**GY59OXK** 

report date: 2024-03-28

MOT #6 2015-09-26 06:19

**MOT test number** 244256430585

**Result** ✓ Passed

MOT #5 2014-10-04 09:02

**MOT test number** 639757674257

Result 

Passed

MOT #4 2014-10-04 09:02

MOT test number 699757974243

**Result** X Failed

**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Pass with rectification** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #3 2013-10-05 10:13

**MOT test number** 378878673470

MOT #2 2013-10-05 09:25

MOT test number 115768073253

**Result** X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #1** 2012-10-09 08:43

**MOT test number** 569473382263

**Result** 
✓ Passed

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



**GY590XK** 

report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-11-25
Last registration	2021-10-11
Complete history	See info



Registration #1	2009-11-25	20 mi
Registration #2	2012-10-09	23.846 mi
Registration #3	2013-10-05	43.370 mi
Registration #4	2013-10-05	43.370 mi
Registration #5	2014-10-04	64.766 mi
Registration #6	2015-09-26	85.836 mi
Registration #7	2016-10-07	113.960 mi
Registration #8	2016-10-07	113.960 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		13.377 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11