



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 5


Date	2022-08-09
Pictures	30
Listing price	View report



source: cargurus.co.uk

Entry 4


Date	2022-04-30
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 3

Date	2021-11-20
Pictures	9
Listing price	View report



source: yesauto.com

Entry 2


Date	2021-10-30
------	------------

Pictures

10

Listing price

[View report](#)



An advertisement for low rate finance. It features a background image of a car dealership with many cars parked. Overlaid on the image is a pink banner with the text "LOW RATE FINANCE" and "ACROSS APPROVED VANS & 4x4s". Below the banner are logos for "BIG VANWORLD" and "MotoNowo FINANCE".

source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date


2021-09-14

Pictures

9

Listing price

[View report](#)



An advertisement for low rate finance. It features a background image of a car dealership with many cars parked. Overlaid on the image is a pink banner with the text "LOW RATE FINANCE" and "ACROSS APPROVED VANS & 4x4s". Below the banner are logos for "BIG VANWORLD" and "MotoNowo FINANCE".

source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-08-30
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	23
Total items failed	0

MOT #6 2023-08-31 15:46

MOT test number 547272074615

Result ✓ Passed

Next expiry date 2024-08-30

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #5 2022-08-10 08:28

MOT test number 769241014648

Result ✓ Passed

**MOT #4** 2021-11-24 17:04**MOT test number** 822206419451**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #3** 2020-11-17 16:02**MOT test number** 648555999903**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**MOT #2** 2020-11-16 14:16**MOT test number** 613811377904**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Items removed from driver's view prior to test**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #12019-11-06 10:10

MOT test number197447140768

Result		✓ Passed
Advice	Rear Service brake fluctuating, but not excessively Both (1.2.1 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	MT66NBA
Plate since	2019-03-28
Current registration	MT66NBA
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-11-30
Last registration	2023-08-31
Complete history	See info



Registration #1	2016-11-30	11 mi
Registration #2	2019-11-06	87.092 mi
Registration #3	2020-11-16	108.663 mi
Registration #4	2020-11-17	108.668 mi
Registration #5	2020-11-17	108.668 mi
Registration #6	2020-11-17	108.668 mi
Registration #7	2020-11-17	108.668 mi
Registration #8	2020-11-17	108.668 mi
Registration #9	2020-11-17	108.668 mi
Registration #10	2020-11-17	108.668 mi
Registration #11	2020-11-17	108.668 mi
Registration #12	2020-11-17	108.668 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MH - C084191LQI