





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) ONE
Colour	Black
Year of manufacture	2012
Top speed	107 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-03-04
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	14
Total items failed	9

MOT #15	2024-03-05 12:49
MOT test number	234847782179
Result	✓ Passed
Next expiry date	2025-03-04

MOT #14	2023-06-13 08:28
MOT test	number 503277364104
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing recommend change (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))

MOT #13	2022-04-22 09:52
MOT test number	201880668832
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2021-04-26 14:52
MOT test number	275819825465
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2021-04-26 14:52

MOT test number 753844698181

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10 2020-09-23 10:21

MOT test number 660966730326

Result \square Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2020-09-23 10:21

MOT test number 106773665296

Result X Failed

Pass with rectification Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2019-08-28 13:04

MOT test number 814283803162

Result Passed

Advice Drive belt worn, but not excessively just light cracking (6.1.7 (c) (i))

MOT #7 2019-08-28 10:57

MOT test number 84882778932

Result X Failed

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Drive belt worn, but not excessively just light cracking (6.1.7 (c) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2018-09-08 14:02

MOT test number 619241828843

Result ✓ Passed

MOT #5 2018-09-08 13:28

MOT test number 782786300821

Result X Failed

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #4 2017-08-23 15:52

MOT test number 289798152889

Result \rightarrow Passed

Advice Service lamp on

Advice Offside Rear tyre split in tread

MOT #3 2017-08-23 11:04

MOT test number 714978661838

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Headlamp aim too high (1.8)

Fail Brake fluid warning lamp illuminated (3.6.G.2)

Advice Offside Rear tyre split in tread

Fail Nearside Headlamp aim too high (1.8)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Service lamp on

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2	2016-08-22 13:22
MOT test number	815773819229
Result	✓ Passed
MOT #1	2015-04-08 17:15
MOT #1 MOT test number	2015-04-08 17:15 377438395052

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NE UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-24
Last registration	2024-03-05
Complete history	See info



Registration #1	2012-03-24	7 mi
Registration #2	2015-04-08	21.677 mi
Registration #3	2016-08-22	31.188 mi
Registration #4	2017-08-23	38.509 mi
Registration #5	2017-08-23	38.509 mi
Registration #6	2018-09-08	45.434 mi
Registration #7	2018-09-08	45.434 mi
Registration #8	2019-08-28	52.745 mi
Registration #9	2019-08-28	52.745 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		
Registration #10		0.00

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles2Engine numberB189J172