





report date: 2024-03-28

### General information

Make	MINI
Model	COOPER S AUTO COOPER S
Colour	Grey
Year of manufacture	2012
Top speed	139 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history


### Entry 1


Date 2021-12-07


Pictures 47

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT hist	orv
----------	-----

MOT expiry date	2024-07-05
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	8
Total items failed	0

MOT #10	2023-07-06 11:13
MOT test number	256158027536
Result	<b>√</b> Passed
Next expiry date	2024-07-05

MOT #9		2022-09-16 10:34
MOT test	number	253281115961
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021	-09-26 09:46
MOT test	number 40	5146532367
Result		✓ Passed
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		(i))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Nearside Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #7	2020-10-02 15:27

**MOT test number** 699417859602

MOT #6 2019-04-23 14:26

**MOT test number** 729910286600

**Result** ✓ Passed

MOT #5 2019-04-23 09:45

**MOT test number** 589909544937

**Result** X Failed

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4 2018-04-24 10:09

**MOT test number** 503011722511

**Result** 
✓ Passed

MOT #3 2017-04-18 09:47

MOT test number 301782783162

**Result** 
✓ Passed

MOT #2 2016-05-05 11:09

**MOT test number** 937604081729

MOT #1 2015-06-11 12:32

**MOT test number** 277442265153

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/11





report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		
Туре		
Damage 2		
Date		
Category		
Туре		



### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



funda soloca

LO12HWA

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MINI had different number plates. ober of plates

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-16
Last registration	2023-07-06
Complete history	See info



Registration #1	2012-06-16	16 mi
Registration #2	2015-06-11	21.015 mi
Registration #3	2016-05-05	25.630 mi
Registration #4	2017-04-18	28.825 mi
Registration #5	2018-04-24	31.810 mi
Registration #6	2019-04-23	35.263 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1155 kg
Max. allowed weight	1630 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 11/11