



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | NISSAN         |
| Model               | PRIMERA FLARE  |
| Colour              | Blue           |
| Year of manufacture | -              |
| Top speed           | 117 mph        |
| 0 - 60 mph          | 11.9 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 114 BHP             |
| Max. torque             | 163 Nm at 4.000 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.4 mpg            |
| Consumption extra urban | 46.3 mpg            |
| Consumption combined    | 38.2 mpg            |



LABEL UNKNOWN

**MOT history**

|                         |  |
|-------------------------|--|
| <b>MOT #16</b>          | 2019-07-08 15:01   |
| <b>MOT test number</b>  | 457156853187   |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2021-01-07   |
| <b>Advice</b>           | Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) |
| <b>Advice</b>           | Exhaust flange corroded center to rear box   |

|                        |                  |
|------------------------|------------------|
| <b>MOT #15</b>         | 2018-06-15 14:23 |
| <b>MOT test number</b> | 618358850866     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #14</b>         | 2017-06-15 14:39 |
| <b>MOT test number</b> | 497576950404     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #13</b>         | 2016-06-15 14:22 |
| <b>MOT test number</b> | 158896968688     |
| <b>Result</b>          | ✓ Passed         |

- Advice** Offside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened rear face (3.5.1i)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened rear face (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12**

2016-06-15 14:22

**MOT test number**

345120723948

**Result****✗ Failed**

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened rear face (3.5.1i)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened rear face (3.5.1i)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Advice** Nearside Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #11**

2016-04-28 17:27

**MOT test number**

162017498033

**Result**

✗ Failed

- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened rear disc face (3.5.1i)
- Fail** Battery insecure (1.9.1)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened rear disc face (3.5.1i)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #10**

2015-02-11 18:03

**MOT test number**

397182845043

**Result**

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #9**

2015-02-11 18:03

**MOT test number**

337222345007

**Result****✗ Failed****Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Nearside Side repeater incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #8**

2014-05-12 16:20

**MOT test number**

857382834169

**Result****✓ Passed****Advice** Side repeater slightly discoloured (1.4.A.2f)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** O/s/r exhaust rubber unattached.

**MOT #7**

2014-05-12 16:20

**MOT test number**

317472734130

**Result****✗ Failed****Notice**

Child seat fitted not allowing full inspection of adult belt

**Pass with rectification**

Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**Advice**

Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**Notice**

O/s/r exhaust rubber unattached.

**Pass with rectification**

Nearside Front position lamp(s) not working (1.1.A.3b)

**Advice**

Side repeater slightly discoloured (1.4.A.2f)

**MOT #6**

2013-04-24 17:50

**MOT test number**

955434013110

**Result****✓ Passed****Notice**

Nail in n/s/r tyre

**Notice**

O/s headlight beam poor

**Notice**

Play in n/s front trackrod end

**Notice**

Both front tyres worn to limits

**MOT #5**

2013-04-24 13:27

**MOT test number**

595074713188

**Result****✗ Failed****Fail**

Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**Notice**

Both front tyres worn to limits

**Notice**

Nail in n/s/r tyre

**Notice**

O/s headlight beam poor

**Notice**

Play in n/s front trackrod end

**MOT #4** 2012-02-20 16:28**MOT test number** 167011052498**Result** ✓ Passed**MOT #3** 2011-02-24 12:57**MOT test number** 109435051473**Result** ✓ Passed**Notice** Both rear tyres worn low**MOT #2** 2010-02-25 13:02**MOT test number** 813446350075**Result** ✓ Passed**Notice** Hand brake has high travel**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2009-05-21 12:24**MOT test number** 841081849111**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2020-01-01    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2020-01-01    |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2006-05-02               |
| Last registration          | 2019-07-08               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2006-05-02 | 25 mi      |
| Registration #2  | 2009-05-21 | 37.797 mi  |
| Registration #3  | 2010-02-25 | 44.371 mi  |
| Registration #4  | 2011-02-24 | 51.979 mi  |
| Registration #5  | 2012-02-20 | 60.772 mi  |
| Registration #6  | 2013-04-24 | 70.269 mi  |
| Registration #7  | 2013-04-24 | 70.271 mi  |
| Registration #8  | 2014-05-12 | 78.355 mi  |
| Registration #9  | 2015-05-20 | 85.377 mi  |
| Registration #10 | 2016-05-20 | 92.377 mi  |
| Registration #11 | 2017-05-20 | 99.377 mi  |
| Registration #12 | 2018-05-20 | 106.377 mi |
| Registration #13 | 2019-05-20 | 113.377 mi |
| Registration #14 | 2020-05-20 | 120.377 mi |
| Registration #15 | 2021-05-20 | 127.377 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1998 mm |
| Height              | 1482 mm |
| Length              | 4567 mm |
| Wheel base          | 2680 mm |
| Kerb weight         | 1361 kg |
| Max. allowed weight | 1810 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                 |        |
|-----------------|--------|
| Number of axles | 2      |
| Engine number   | 448099 |