



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	Grey
Year of manufacture	2015
Top speed	150 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	16.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 75 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-04
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	48
Total items failed	6

MOT #9	2023-04-05 15:28
--------	------------------

MOT test number	703253062574
-----------------	--------------

Result	✓ Passed
Next expiry date	2024-04-04
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone bush bonding (5.3.4 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear heat shield loose
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge wearing on edge (5.2.3 (e))

**MOT #8**

2023-04-05 13:32

**MOT test number**

716972393067

**Result****✗ Failed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
- Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear heat shield loose
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear at rear (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone bush bonding (5.3.4 (a) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps inop (4.7.1 (b) (ii))

**MOT #7**

2022-02-01 16:21

**MOT test number**

336084469634

**Result**

✓ Passed

- Advice** Central Brake pipe corroded, covered in grease or other material Both front to rear at axle (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Outer Edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Approx. 2mm (5.2.3 (e))

**MOT #6**

2022-02-01 09:25

**MOT test number**

869812987031

**Result**

✗ Failed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Outer Edge (5.2.3 (e))
- Advice** Central Brake pipe corroded, covered in grease or other material Both front to rear at axle (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Approx. 2mm (5.2.3 (e))
- Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #5** 2021-01-19 16:27**MOT test number** 729566143180**Result** ✓ Passed**MOT #4** 2020-05-11 10:06**MOT test number** 663268690006**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #3** 2019-06-13 16:16**MOT test number** 391884730474**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2019-05-28 08:14**MOT test number** 745701510587**Result** ✗ Failed**Fail** Offside Windscreen wiper missing (3.4 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction flashing intermittently (8.2.2.2 (g))**Advice** Offside Rear Nail in tyre**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #1	2018-05-21 10:33
MOT test number	172263179475
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-18
Last registration	2023-04-05
Complete history	<a href="#">See info</a>



Registration #1	2015-06-18	9 mi
Registration #2	2018-05-21	25.854 mi
Registration #3	2019-05-28	37.997 mi
Registration #4	2019-06-13	37.997 mi
Registration #5	2020-05-11	49.935 mi
Registration #6	2021-01-19	56.128 mi
Registration #7	2023-04-05	56.128 mi
Registration #8	2023-04-05	56.128 mi
Registration #9	2023-04-05	56.128 mi
Registration #10	2023-04-05	56.128 mi
Registration #11	2023-04-05	56.128 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2138 mm
Height	1805 mm
Length	4282 mm
Wheel base	2 mm
Kerb weight	1205 kg
Max. allowed weight	1884 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2

Number of axles	2
Engine number	D579568