




report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 2

Date	2022-02-13
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2022-02-04
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	20
Total items failed	5

MOT #15	2023-09-08 17:44
MOT test number	901564006865
Result	✓ Passed
Next expiry date	2024-09-07

MOT #14	2023-09-08 14:58
MOT test number	148262764190
Result	✗ Failed
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))	

MOT #13	2021-12-08 17:10
MOT test number	149488038944
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Minor Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

**MOT #12** 2021-12-08 17:10**MOT test number** 303480248790**Result** ✗ Failed**Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2020-12-08 18:07**MOT test number** 884068302353**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2019-06-10 17:25**MOT test number** 932945041098**Result** ✓ Passed**MOT #9** 2019-06-10 15:44**MOT test number** 678498623504**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #8** 2018-04-24 15:35**MOT test number** 582678715317**Result** ✓ Passed**MOT #7** 2017-03-31 15:00**MOT test number** 121440611729**Result** ✓ Passed**MOT #6** 2017-03-28 14:58**MOT test number** 253246036401**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Lower Front suspension has excessive movement at a suspension ball joint (2.5.A.1c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #5** 2016-04-08 11:57**MOT test number** 615689631467**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2015-04-28 14:09**MOT test number** 805318015124**Result** ✓ Passed**MOT #3** 2014-03-27 13:03**MOT test number** 455456284083**Result** ✓ Passed



MOT #2	2014-03-26 12:44
MOT test number	515035484029
Result	✗ Failed
<div>Fail</div> Offside Rear Shock absorber has a serious fluid leak (2.7.3)	

MOT #1	2013-04-26 10:27
MOT test number	976066313166
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
7 September 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	PE10WHU
Plate since	2019-03-29
Current registration	PE10WHU
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-15
Last registration	2023-09-08
Complete history	See info



Registration #1	2010-03-15	8 mi
Registration #2	2013-04-26	16.456 mi
Registration #3	2014-03-26	22.175 mi
Registration #4	2014-03-27	22.175 mi
Registration #5	2015-04-28	27.511 mi
Registration #6	2016-04-08	33.953 mi
Registration #7	2017-03-28	39.672 mi
Registration #8	2017-03-31	39.672 mi
Registration #9	2018-04-24	42.201 mi
Registration #10	2019-05-29	45.377 mi
Registration #11	2019-05-29	45.377 mi
Registration #12	2019-05-29	45.377 mi
Registration #13	2019-05-29	45.377 mi
Registration #14	2019-05-29	45.377 mi
Registration #15	2019-05-29	45.377 mi
Registration #16	2019-05-29	45.377 mi
Registration #17	2019-05-29	45.377 mi
Registration #18	2019-05-29	45.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1237765