



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 BUSINESS EDITION
Colour	Blue
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-08-31
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	16
Total items failed	0

MOT #8	2023-09-12 11:15
MOT test number	212868606087
Result	✓ Passed
Next expiry date	2024-09-15
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #7	2022-09-09 08:00
MOT test number	237424509996
Result	✓ Passed
Advice	No emissions pick-up 61c

MOT #6	2021-09-16 12:05
MOT test number	229825251602
Result	✓ Passed

MOT #5	2021-09-16 08:35
MOT test number	775069935524
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #4** 2020-12-09 12:14**MOT test number** 206410139408**Result** ✓ Passed**MOT #3** 2019-12-10 14:54**MOT test number** 443838256898**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2018-11-29 13:40**MOT test number** 432515118758**Result** ✓ Passed**MOT #1** 2018-11-21 13:31**MOT test number** 689278337274**Result** ✗ Failed

- MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))
- MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-12-18
Last registration	2023-09-12
Complete history	See info



Registration #1	2015-12-18	28 mi
Registration #2	2018-11-21	61.813 mi
Registration #3	2018-11-29	61.825 mi
Registration #4	2019-12-10	82.861 mi
Registration #5	2020-12-09	102.308 mi
Registration #6	2021-05-20	121.277 mi
Registration #7	2021-05-20	121.277 mi
Registration #8	2021-05-20	121.277 mi
Registration #9	2021-05-20	121.277 mi
Registration #10	2023-09-12	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1703 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1343940