





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	White
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 4

Date 2021-07-22

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date 2021-07-18

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date 2021-07-17

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-08-19
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #6	2023-08-17 09:53
MOT test number	915187245596
Result	✓ Passed
Next expiry date	2024-08-19
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2022-08-04 08:26
MOT test number	930721902117
Result	✓ Passed

MOT #4	2021-08-20 14:09
MOT test	number 370929523545
Result	✓ Passed
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3		2021-02-04 12:28
MOT test	number	285220016899
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2021-02-04 12:28 **MOT test number** 117288928208 Result × Failed Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

698958837177

Result

Advice Front front pads low

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim	1.00
Owner	historv
OWITCH	1113601)

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NEZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-02-08
Last registration	2023-08-17
Complete history	See info



Registration #1	2017-02-08	24 mi
Registration #2	2020-01-24	35.225 mi
Registration #3	2021-02-04	41.149 mi
Registration #4	2021-02-04	41.149 mi
Registration #5		11,177 66
Registration #6		11.177 es
Registration #7		11.777 es
Registration #8		11.117 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		9.777 sc

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles 2

Engine number D4FBGZ107277