





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER D CLUBMAN
Colour	Red
Year of manufacture	2011
Top speed	122 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-05-17
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #13	2024-04-25 08:34
MOT test number	204303187761
Result	✓ Passed
Next expiry date	2025-05-17

MOT #12	2023-05-18 12:25
MOT test number	398318804086
Result	✓ Passed

MOT #11		2023-05-17 12:44
MOT test	number	883446505375
Result		🗙 Failed
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4

MAJOR Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 2/11



Advice

YK610PC report date: 2024-03-28

MOT #10 2022-05-03 09:49

MOT test number 149096262368

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2021-05-18 12:13

MOT test number 474843080248

Result ✓ Passed

MOT #8 2020-07-30 14:25

MOT test number 101130586333

Result Passed

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2020-07-29 13:55

MOT test number 476104835165

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2019-06-04 08:43

MOT test number 841989958377

Result

Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

433883418310

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))

 MOT #4
 2017-05-23 08:38

 MOT test number
 855750604699

 Result
 ✓ Passed

 MOT #3
 2016-06-07 08:46

 MOT test number
 810785515855

 Result
 ✓ Passed

 Advice
 Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2015-06-18 18:03
MOT test number	939539765103
Result	✓ Passed

MOT #1	2014-09-01 13:04
MOT test number	997304444200
Result	✓ Passed
Notice Centre rear seat belt not tested	
Notice Drivers wiper blade splitting	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK WEST
Plate since	
Current registration	UK UK
Finite since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-20
Last registration	2024-04-25
Complete history	See info



Registration #1	2011-09-20	17 mi
Registration #2	2014-09-01	23.164 mi
Registration #3	2015-06-18	29.308 mi
Registration #4	2016-06-07	36.335 mi
Registration #5	2017-05-23	41.990 mi
Registration #6	2018-06-05	48.494 mi
Registration #7	2019-06-04	54.378 mi
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1185 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Engine number

70667890