





General information

| Make | CITROEN |
|---------------------|-----------------------|
| Model | DS3 E-HDI DSTYLE PLUS |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 113 mph |
| 0 - 60 mph | 12.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 64.2 mpg |
| Consumption extra urban | 85.6 mpg |
| Consumption combined | 76.4 mpg |
| CO2 emission | 95 g/km |
| CO2 label | А |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-09-17 |
| Pictures | 2 |
| Listing price | View report |
| | |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-11-07 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 22 |
| Total items failed | 6 |

| MOT #11 | | 2023-11-03 10:55 |
|-----------|--|-----------------------|
| MOT test | number | 949157770492 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-11-07 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened both si | des (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |

MOT #10

| мот | test | number |
|-----|-------|----------|
| | LC JL | IIGHINCI |

| Result | 🗙 Failed |
|---|-----------|
| Fail Nearside Front Headlamp aim too low (4.1.2 (a)) | |
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer pre- ingress of dirt (6.1.7 (g) (ii)) | vents the |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a |) (ii)) |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |

2023-11-03 09:10 478621119944



| MOT #9 | | 2022-11-07 10:43 |
|----------|--|------------------|
| MOT test | number | 852566805942 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |

MOT #8 2022-11-07 09:19 MOT test number 568115701673 Result X Failed Fail Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

| MOT #7 | 2021-11-08 16:04 |
|---|------------------|
| MOT test number | 740492634191 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2020-10-12 14:38 |
| MOT test number | 134896455250 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-10-08 09:31 |
| MOT test number | 796173391378 |
| Result | 🗙 Failed |
| Fail Offside Headlamp not working on dipped beam CONNECTOR OVERHEATED/MELTED (4.1.1 (a) (ii)) | |







| MOT #4 | | 2019-10-19 11:18 |
|-------------------------|--|------------------|
| MOT test | number | 563725659792 |
| Result | | ✓ Passed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1 | .1.14 (a) (ii)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Rear Exhaust mounting defective rear exhaust section front mount (6.1.2 (a)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Minor (4.7.1 (b) | Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (i)) | or light sources |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1 | .14 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | 2018-10-19 09:16 |
|-----------------|------------------|
| MOT test number | 796010564349 |
| Result | ✓ Passed |

| MOT #2 | 2018-10-18 09:11 |
|---|------------------|
| MOT test number | 670716082768 |
| Result | 🗙 Failed |
| Advice Offside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Advice Nearside Rear Nail in tyre | |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Oil leak, but not excessive Oil leak top of intercooler. (8.4.1 (a) (i)) | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/45/17 88V | (5.2.3 (d) (ii)) |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |





| MOT #1 | 2017-11-11 09:23 |
|-----------------|------------------|
| MOT test number | 119742804488 |
| Result | ✓ Passed |



KM64YTD report date: 2024-03-28

Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | ✓ MOT Expires: 7 November 2024 |
|---|---|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 7 November 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | · · · |
| Category | AMPL |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



KM64YTD report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2014-11-27 |
| Last registration | 2023-11-03 |
| Complete history | See info |



| Registration #1 | 2014-11-27 | 22 mi |
|------------------|------------|------------|
| Registration #2 | 2017-11-11 | 28.683 mi |
| Registration #3 | 2018-10-18 | 33.037 mi |
| Registration #4 | 2018-10-19 | 33.040 mi |
| Registration #5 | 2019-10-19 | 45.133 mi |
| Registration #6 | 2020-10-08 | 52.008 mi |
| Registration #7 | 2020-10-12 | 52.008 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.117 esi |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1728 mm |
| Height | 1524 mm |
| Length | 3941 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1085 kg |
| Max. allowed weight | 1602 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 48 I |
| | 48 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 3 |