



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 8V ACTIVE
Colour	Silver
Year of manufacture	2008
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-12
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	29
Total items failed	12

MOT #192024-01-15 14:50

MOT test number110100481897

Result✓ Passed

Next expiry date2025-01-14

- Advice**Central Lower Gearbox mounting defective
- Advice**Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice**Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement Wishbone (5.3.4 (a) (i))
- Advice**Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Minor**Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice**Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement Wishbone (5.3.4 (a) (i))

**MOT #18**

2024-01-15 12:32

**MOT test number**

214766130606

**Result**

✗ Failed

**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement Wishbone (5.3.4 (a) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Central Lower Gearbox mounting defective**Fail** Offside Rear Lower Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement Wishbone (5.3.4 (a) (i))**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #17**

2023-01-05 14:42

**MOT test number**

999878533869

**Result**

✓ Passed

**MOT #16**

2022-02-10 17:34

**MOT test number**

910445756539

**Result**

✓ Passed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #15**

2022-02-10 14:56

**MOT test number**

818237418369

**Result**

✗ Failed

**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14** 2020-12-29 16:03**MOT test number** 526561495128**Result** ✓ Passed**MOT #13** 2020-01-02 14:24**MOT test number** 136553759743**Result** ✓ Passed**MOT #12** 2020-01-02 10:16**MOT test number** 477523566074**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #11** 2018-12-28 14:45**MOT test number** 907370605469**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #10** 2017-12-29 14:57**MOT test number** 861795550932**Result** ✓ Passed**MOT #9** 2017-01-05 10:58**MOT test number** 939789311552**Result** ✓ Passed**Advice** Offside Front tyre worn on edges**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #8** 2015-11-10 13:26**MOT test number** 461167876666**Result** ✓ Passed**Advice** Rear boot struts soft**Advice** Exhaust system is corrodedd**MOT #7** 2015-11-10 13:26**MOT test number** 600740108510**Result** ✗ Failed**Advice** Rear boot struts soft**Advice** Exhaust system is corrodedd**Pass with rectification** Offside Rear Brake pipe fouled by moving parts (3.6.B.2a)**MOT #6** 2014-11-19 08:37**MOT test number** 856053824331**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #5**

2014-11-13 14:49

**MOT test number**

365757514311

**Result****✗ Failed****Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**Advice**

Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Fail**

Offside Registration plate lamp not working (1.1.C.1d)

**Fail**

Nearside Headlamp aim too low (1.8)

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail**

Offside Headlamp aim too high (1.8)

**Fail**

Offside Rear Brake pipe excessively damaged (3.6.B.2c)

**MOT #4**

2013-11-18 11:59

**MOT test number**

486552323479

**Result****✓ Passed****MOT #3**

2012-11-13 11:35

**MOT test number**

156438112377

**Result****✓ Passed****MOT #2**

2011-11-18 12:58

**MOT test number**

416392521368

**Result****✓ Passed**



MOT #1	2011-11-18 11:46
MOT test number	736232621341
Result	✗ Failed
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
14 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	14 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-11-18
Last registration	2024-01-15
Complete history	<a href="#">See info</a>



Registration #1	2008-11-18	8 mi
Registration #2	2011-11-18	38.230 mi
Registration #3	2011-11-18	38.230 mi
Registration #4	2012-11-13	45.226 mi
Registration #5	2013-11-18	49.882 mi
Registration #6	2014-11-13	54.855 mi
Registration #7	2014-11-19	54.856 mi
Registration #8	2015-11-10	59.963 mi
Registration #9	2015-11-10	59.963 mi
Registration #10	2017-01-05	65.517 mi
Registration #11	2017-12-29	72.731 mi
Registration #12	2019-01-01	75.000 mi
Registration #13	2019-01-01	75.000 mi
Registration #14	2019-01-01	75.000 mi
Registration #15	2019-01-01	75.000 mi
Registration #16	2019-01-01	75.000 mi
Registration #17	2019-01-01	75.000 mi
Registration #18	2019-01-01	75.000 mi
Registration #19	2019-01-01	75.000 mi
Registration #20	2019-01-01	75.000 mi
Registration #21	2019-01-01	75.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4336861