





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT
Colour	Blue
Year of manufacture	2018
Top speed	94 mph
0 - 100 km/h	11.6 seconds
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2022-02-06

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-04
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	11
Total items failed	4

MOT #7	2024-02-05 15:53
MOT test number	137409925215
Result	✓ Passed
Next expiry date	2025-02-04
Minor Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))	

MOT #6	2024-02-02 12:46
MOT test number	813474395840
Result	∨ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

MAJOR Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5	2023-01-20 12:18
MOT test number	764196627055
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4

MOT test number

Result

Pass with rectification

Offside Rear reflector missing (4.8.2 (a) (ii))

Pass with rectification

Nearside Rear reflector missing (4.8.2 (a) (ii))

 MOT #3
 2022-02-05 08:36

 MOT test number
 841020596845

 Result
 \(\rightarrow \) Passed

MOT test number

Result

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Slight lip to front brake discs - pads good, approx. 6mm thick

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2021-05-11 15:44 **MOT** test number 967646008495 Result × Failed Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) **Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) Advice Slight lip to front brake discs - pads good, approx. 6mm thick **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



GF18YKP
report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 8/11



GF18YKP
report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-16
Last registration	2024-02-05
Complete history	See info



Registration #1	2018-05-16	15 mi
Registration #2	2021-05-11	30.958 mi
Registration #3	2021-05-11	30.958 mi
Registration #4	2022-02-05	36.610 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2397 mm
Height	1990 mm
Length	5304 mm
Wheel base	3400 mm
Kerb weight	1942 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CXGB122204