






report date: 2024-03-28

General information

Make	FORD
Model	FOCUS TITANIUM X
Colour	Bronze
Year of manufacture	-
Top speed	141 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	203 BHP
Max. torque	300 Nm at 1.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/11



Internet history

Entry 2

	Date	2023-12-11
--	------	------------

Pictures 8









source: g3remarketing.co.uk

Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

Advice

 MOT #13
 2022-01-31 10:40

 MOT test number
 859048105640

 Result
 ✓ Passed

 Next expiry date
 2023-02-04

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

MOT test number

245763769878

Result

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT test number

657391917903

Result

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Rear Exhaust system insecure (6.1.2 (a))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #10

MOT test number

Result

MOT #9

2018-09-13 10:46

MOT test number

477605784541

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



MJ10HCV

report date: 2024-03-28

MOT #8	2017-08-15 12:50
MOT test number	339707293919

MOT #7 2016-10-15 09:08

MOT test number 693200571298

Result

Passed

MOT #6 2016-08-04 15:46

MOT test number 419780833513

Result
✓ Passed

MOT #5 2016-08-04 09:58

MOT test number 559428580473

Result × Failed

Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)

MOT #4 2015-08-28 14:28

MOT test number 403756533507

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 4/11



MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear rear brake excessively fluctuating (3.7.B.3)

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #2	2014-09-01 09:13
MOT #2	2014-09-01 09.13
MOT test number	945594644266
Result	✓ Passed
MOT #1	2013-08-30 13:49
MOT test number	378152043229
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Notice Nearside front tyre has splits on inner sidewall	

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-28
Last registration	2022-01-31
Complete history	See info



Registration #1	2010-05-28	16 mi
Registration #2	2013-08-30	23.701 mi
Registration #3	2014-09-01	31.861 mi
Registration #4	2015-08-25	36.270 mi
Registration #5	2015-08-28	36.327 mi
Registration #6	2016-08-04	39.717 mi
Registration #7	2016-08-04	39.717 mi
Registration #8	2016-10-15	39.964 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1886 mm
Height	1512 mm
Length	4830 mm
Wheel base	2850 mm
Kerb weight	1602 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/