




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SHUTTLE SE LWB 130TDI
Colour	Blue
Year of manufacture	2005
Top speed	102 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.4 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.7 mpg
CO2 emission	251 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)

**MOT history****MOT expiry date** 2021-06-04**MOT pass rate** 71 %**MOT passed** 12**Failed MOT tests** 5**Total advice items** 26**Total items failed** 14**MOT #17** 2020-06-05 10:44**MOT test number** 882853101189**Result** ✓ Passed**Next expiry date** 2021-06-04**Minor** Front Suspension component ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))**MOT #16** 2020-06-04 12:01**MOT test number** 418507113888**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Front Suspension component ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**MOT #15**

2019-04-16 12:39

MOT test number

683500760924

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre wearing smooth on outer and inner edges (5.2.3 (e))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Marked (5.3.4 (a) (i))

MOT #14

2019-04-15 12:12

MOT test number

392840761408

Result

✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn Marked (5.3.4 (a) (i))

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Marked (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre wearing smooth on outer and inner edges (5.2.3 (e))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))

Fail Offside Rear Stop lamp(s) showing white light to the rear Stop lamp lens broken has sharp edges. (4.3.3 (a) (ii))

MOT #13

2018-04-13 08:32

MOT test number

811605719060

Result

✓ Passed

MOT #12

2017-03-24 16:54

MOT test number

893751851120

Result

✓ Passed

Advice Spare tyre defective

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11**

2017-03-24 09:52

MOT test number

891720638688

Result

✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Spare tyre defective**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #10**

2016-04-15 09:44

MOT test number

116524476437

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)**Advice** 1 child seat centre front and 2 child seats rear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9**

2015-04-15 10:24

MOT test number

889785905131

Result

✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt**Notice** Service light on**Notice** Air filter clip lose

**MOT #8** 2014-04-16 15:30**MOT test number** 246386604410**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2013-04-19 14:53**MOT test number** 809169803118**Result** ✓ Passed**Notice** Scuffing to nearside front & rear tyres**MOT #6** 2013-04-19 11:25**MOT test number** 876979403159**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Scuffing to nearside front & rear tyres**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2012-02-28 11:48**MOT test number** 178319952436**Result** ✓ Passed**MOT #4** 2011-02-28 14:29**MOT test number** 727879251024**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #3	2010-02-24 11:37
MOT test number	150665950490
Result	✓ Passed
MOT #2	2009-02-27 14:45
MOT test number	322328959069
Result	✓ Passed
MOT #1	2009-02-27 14:45
MOT test number	121348359026
Result	✗ Failed
Pass with rectification	Offside Side repeater insecure (1.4.A.2b)



Tax & MOT check

X

Untaxed

Tax expired:
1 July 2020

X

MOT

Expired:
4 June 2021

Tax status	Expired at 1 July 2020
Days left	1399 days too late
MOT expiry date	4 June 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LS05FHJ
Plate since	2019-03-29
Current registration	 LS05FHJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-06-30
Last registration	2020-06-05
Complete history	See info



Registration #1	2005-06-30	20 mi
Registration #2	2009-02-27	45.878 mi
Registration #3	2010-02-24	53.267 mi
Registration #4	2011-02-28	59.053 mi
Registration #5	2012-02-28	65.571 mi
Registration #6	2013-04-19	74.077 mi
Registration #7	2013-04-19	74.077 mi
Registration #8	2014-04-16	84.050 mi
Registration #9	2015-04-15	89.397 mi
Registration #10	2016-04-15	95.777 mi
Registration #11	2017-04-15	102.157 mi
Registration #12	2018-04-15	108.537 mi
Registration #13	2019-04-15	114.917 mi
Registration #14	2020-06-05	121.297 mi
Registration #15	2020-06-05	121.297 mi
Registration #16	2020-06-05	121.297 mi
Registration #17	2020-06-05	121.297 mi
Registration #18	2020-06-05	121.297 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	5290 mm
Kerb weight	2205 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	8
Engine number	AXD 081060