



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 280
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	300 Nm at 3.500 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.2 mpg
Consumption combined	29.7 mpg
CO2 emission	222 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-27
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-28
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	18
Total items failed	2

MOT #16	2023-09-24 09:32
MOT test number	449424144282
Result	✓ Passed
Next expiry date	2024-09-28

MOT #15	2022-09-15 12:16
MOT test number	660182898684
Result	✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #14	2021-09-15 12:09
MOT test number	116691520603
Result	✓ Passed

MOT #13	2020-09-29 15:29
MOT test number	603922308863
Result	✓ Passed

**MOT #12** 2020-02-07 15:21**MOT test number** 392810908075**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2017-12-18 16:24**MOT test number** 992933999806**Result** ✓ Passed**MOT #10** 2016-12-02 08:38**MOT test number** 302976244382**Result** ✓ Passed**MOT #9** 2015-12-24 08:01**MOT test number** 312118190138**Result** ✓ Passed**MOT #8** 2014-12-03 12:03**MOT test number** 149757234349**Result** ✓ Passed**MOT #7** 2014-12-02 11:17**MOT test number** 327006634322**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)

**MOT #6** 2014-04-26 09:26**MOT test number** 889816114134**Result** ✓ Passed

Advice Offside Inner Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Inner Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #5 2013-04-27 10:25**MOT test number** 427757813169**Result** ✓ Passed

Advice Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-04-28 09:47**MOT test number** 615469812161**Result** ✓ Passed

Advice Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Offside front tyre damage to inner edge

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-04-09 09:23**MOT test number** 427679591064**Result** ✓ Passed



MOT #2	2010-04-29 16:21
MOT test number	804919910140
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-10-19 15:33
MOT test number	561222099248
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-10-31
Last registration	2023-09-24
Complete history	See info



Registration #1	2006-10-31	6 mi
Registration #2	2009-10-19	18.564 mi
Registration #3	2010-04-29	22.889 mi
Registration #4	2011-04-09	30.511 mi
Registration #5	2012-04-28	36.578 mi
Registration #6	2013-04-27	42.504 mi
Registration #7	2014-04-26	46.835 mi
Registration #8	2014-12-02	49.213 mi
Registration #9	2014-12-03	49.216 mi
Registration #10	2015-05-20	49.216 mi
Registration #11	2015-05-20	49.216 mi
Registration #12	2015-05-20	49.216 mi
Registration #13	2015-05-20	49.216 mi
Registration #14	2015-05-20	49.216 mi
Registration #15	2015-05-20	49.216 mi
Registration #16	2015-05-20	49.216 mi
Registration #17	2015-05-20	49.216 mi
Registration #18	2015-05-20	49.216 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1460 kg
Max. allowed weight	1755 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27294230319669