





report date: 2024-03-29

## General information

Make	MINI
Model	PACEMAN COOPER S ALL4
Colour	White
Year of manufacture	2014
Top speed	132 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/12



**AV14GYE** 

report date: 2024-03-29

## Internet history


#### Entry 4

Date 2023-01-15

Pictures 13

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 3

Date 2022-02-04

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 2

Date 2021-12-14


Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #10	2023-10-11 11:37
MOT test number	573985103306
Result	✓ Passed
Next expiry date	2024-10-13

MOT #9	2023-10-11 08:24
MOT test number	431056870055
Result	<b>X</b> Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #8		2022-10-06 09:35
MOT test i	number	161674130391
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing in between to	read (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



**AV14GYE** 

report date: 2024-03-29

MOT #7		2021-10-14 14:25
MOT test	number	337685932462
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front strut top mount starting to crack	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front strut top mount starting to crack	

MOT #6	2020-09-25 11:31
MOT test number	984563085738
Result	<b>✓</b> Passed
MOT #5	2019-09-27 09:45
MOT test number	185724924183
Result	<b>✓</b> Passed
MOT #4	2018-09-28 08:55
MOT test number	169202800482
Result	<b>✓</b> Passed
MOT #3	2017-09-12 16:58
MOT test number	172421532694
Result	✓ Passed
MOT #2	2017-05-05 09:06
MOT test number	355971451745
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

CarCheck.co.uk page 4/12



MOT #1

MOT test number

438424104668

Result

Advice Nearside Rear Nail in tyre

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	13 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h	
THE STATE OF THE S	
************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK NE
Flate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-04-29
Last registration	2023-10-11
Complete history	See info



Registration #1	2014-04-29	8 mi
Registration #2	2017-05-05	17.618 mi
Registration #3	2017-05-05	17.618 mi
Registration #4	2017-09-12	17.719 mi
Registration #5	2018-09-28	22.983 mi
Registration #6	2019-09-27	26.923 mi
Registration #7	2020-09-25	30.030 mi
Registration #8	2021-10-14	30.803 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1786 mm
Height	1522 mm
Length	4115 mm
Wheel base	2596 mm
Kerb weight	1370 kg
Max. allowed weight	1840 kg

## Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA072J648