



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2010
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-31
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-25
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	11
Total items failed	12

MOT #13 2023-05-26 09:31

MOT test number 707217463294

Result ✓ Passed

Next expiry date 2024-05-25

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #12 2021-11-05 19:09

MOT test number 961424950853

Result ✗ Failed

- Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Front Exhaust has a major leak of exhaust gases Flexi (6.1.2 (a))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Fail** Offside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))

**MOT #11** 2020-10-12 16:46**MOT test number** 998345436919**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10** 2020-10-09 15:46**MOT test number** 122269747684**Result** ✗ Failed**Fail** Offside Rear Hydraulic brake cylinder leaking hydraulic fluid caliper (1.1.16 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #9** 2019-10-02 15:20**MOT test number** 496902757454**Result** ✓ Passed**MOT #8** 2018-10-04 12:15**MOT test number** 825791100490**Result** ✓ Passed**MOT #7** 2018-09-27 10:19**MOT test number** 540636312282**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Power steering pipe/hose leaking On Rack (2.1.5 (a))

**MOT #6** 2017-09-25 08:57**MOT test number** 692206443655**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Oil leak**Advice** Exhaust bracket broken but systems still supported**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-09-01 13:11**MOT test number** 646957658363**Result** ✓ Passed**MOT #4** 2015-09-14 16:06**MOT test number** 995341268168**Result** ✓ Passed**MOT #3** 2014-09-01 15:18**MOT test number** 388204044201**Result** ✓ Passed**MOT #2** 2014-09-01 12:57**MOT test number** 697214744277**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #1** 2013-09-09 15:24**MOT test number** 745652253227**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
25 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	25 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-30
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	22 mi
Registration #2	2013-09-09	39.484 mi
Registration #3	2014-09-01	57.768 mi
Registration #4	2014-09-01	57.768 mi
Registration #5	2015-09-14	73.815 mi
Registration #6	2016-09-01	85.517 mi
Registration #7	2017-09-25	94.559 mi
Registration #8	2018-09-27	101.025 mi
Registration #9	2019-05-29	111.277 mi
Registration #10	2019-05-29	111.277 mi
Registration #11	2019-05-29	111.277 mi
Registration #12	2019-05-29	111.277 mi
Registration #13	2019-05-29	111.277 mi
Registration #14	2019-05-29	111.277 mi
Registration #15	2019-05-29	111.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	204462