



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1	
Date	2022-02-13
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-12-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	8

MOT #9	2022-12-02 14:27
MOT test number	838545960644
Result	✓ Passed
Next expiry date	2023-12-01

MOT #8	2021-11-13 11:54
MOT test number	465148414104
Result	✓ Passed

MOT #7	2020-11-26 15:05
MOT test number	490979637466
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**MOT #6** 2020-11-26 14:25**MOT test number** 556966574890**Result** ✗ Failed**Fail** Headlamp aim not tested (4.1.2 (b))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2018-07-03 12:25**MOT test number** 875949844170**Result** ✓ Passed**MOT #4** 2018-07-02 08:45**MOT test number** 698094208172**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge Both front tyres (5.2.3 (e))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))



MOT #3	2017-06-12 11:07
MOT test number	846165994688
Result	✓ Passed
Advice	Tyre worn close to the legal limit Both front (4.1.E.1)

MOT #2	2016-06-14 13:08
MOT test number	334082014836
Result	✓ Passed
Advice	Nearside Front Lower Tie bar/rod has slight play in a ball joint (2.4.G.2)
Advice	Emission too clean to record

MOT #1	2015-05-08 10:54
MOT test number	457158425148
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
1 December 2023

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	1 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-28
Current registration	 *****
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-06-21
Last registration	2022-12-02
Complete history	See info



Registration #1	2012-06-21	9 mi
Registration #2	2015-05-08	35.806 mi
Registration #3	2016-06-14	62.845 mi
Registration #4	2017-06-12	94.604 mi
Registration #5	2018-07-02	127.758 mi
Registration #6	2018-07-03	127.758 mi
Registration #7	2019-05-20	151.277 mi
Registration #8	2019-05-20	151.277 mi
Registration #9	2019-05-20	151.277 mi
Registration #10	2019-05-20	151.277 mi
Registration #11	2019-05-20	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719