





report date: 2024-03-29

### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Gold
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/15



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-09-03

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-04-01
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	41
Total items failed	16

MOT #23	2024-04-02 11:53
MOT test number	641798680630
Result	✓ Passed
Next expiry date	2025-04-01
Minor Front Headlamp lens slightly defective Both side (4.1.1 (b) (i))	

MOT #22	2023-03-11 10:39
MOT test number	356551748226
Result	<b>✓</b> Passed

MOT #21		2022-03-08 15:22
MOT test	number	363835395410
Result		✓ Passed
Advice	N/s rear tyre sidewall poor condition	
Advice	Slight interaction on n/s rear lamp	
Advice	Nail in n/s rear tyre	
Advice	Play in both steering rack ends	

CarCheck.co.uk page 3/15



**Advice** 

N/s rear tyre sidewall poor condition

**GU070PT** 

report date: 2024-03-29

MOT test number

Result

Advice

Slight interaction on n/s rear lamp

Fail

Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))

Advice

Nail in n/s rear tyre

Advice

Play in both steering rack ends

MOT #19

MOT test number

805584466835

Result

Advice Nearside Front Play in steering rack inner joint(s)

Advice Offside Front Play in steering rack inner joint(s)

MOT #18

MOT test number

458552116142

Result

Advice Play in steering rack inner joint(s)

MOT #17

MOT test number

523578050324

Result

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Oil leak

Advice Inner Track rod end ball joint has slight play both (2.1.3 (b) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #16** 2019-01-29 10:17

**MOT test number** 713506900281

**Result** X Failed

Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

**Advice** Inner Track rod end ball joint has slight play both (2.1.3 (b) (i))

**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))

**Fail** Offside Front Seat belt retracting mechanism defective (7.1.2 (e))

**Advice** Oil leak

**MOT #15** 2018-02-19 10:05

**MOT test number** 571149577280

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Front Play in steering rack inner joint(s)

**MOT #14** 2017-03-20 12:29

MOT test number 538180865611

Result 

Passed

MOT #13 2017-03-20 12:29

**MOT test number** 333535283489

Result X Failed

Pass with rectification Nearside Rear position lamp(s) adversely affected by the operation of another

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Rear position lamp(s) adversely affected by the operation of another

lamp (1.1.A.3f)

lamp (1.1.A.3f)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #12 2016-02-02 16:04

**MOT test number** 896410085197

**MOT #11** 2015-02-19 15:01

MOT test number 869610955085

**Result** 
✓ Passed

**Notice** Under-trays fitted obscuring some underside components

**Notice** Small cut nearside front tyre

MOT #10 2015-02-19 10:14

**MOT test number** 538700255063

**Result** X Failed

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**Notice** Under-trays fitted obscuring some underside components

**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

**Notice** Small cut nearside front tyre

MOT #9 2014-01-30 09:13

MOT test number 175640734494

Result 

Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2013-03-14 10:37

MOT test number 386433473032

Notice Interior mirror for size and drivers view of road\all brake discs wearing

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #7 2013-03-14 10:37

**MOT test number** 915463473086

Result × Failed

**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Notice Interior mirror for size and drivers view of road\all brake discs wearing

MOT #6 2012-03-06 15:00

MOT test number 778926962080

Result \( \sqrt{Passed} \)

**MOT #5** 2012-03-05 11:27

**MOT test number** 179705762440

**Result** X Failed

Fail Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

MOT #4 2011-03-31 10:36

MOT test number 259980491030

Result \( \sqrt{Passed} \)

**Notice** Offside inner steering arm has slight play

**Notice** Undertray fitted

**Notice** Rear tyres perrishing on outter walls

CarCheck.co.uk page 7/15



report date: 2024-03-29



MOT #2		2010-03-09 11:52
MOT test	number	162448860041
Result		✓ Passed
Notice	Offside front steering inner coaxle has slight pley	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Undertray fitted	
Advice	Rear brake disc slightly pitted (3.5.1h)	

MOT #1		2010-03-08 11:48
MOT test	number	120717060039
Result		<b>×</b> Failed
<b>Fail</b> N (4.1.D.1a)	learside Front Tyre has a cut in excess of the requirements deep enough to real	ach the ply or cords
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Offside front steering inner coaxle has slight pley	
Advice	Rear brake disc slightly pitted (3.5.1h)	
Notice	Undertray fitted	

CarCheck.co.uk page 8/15



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	1 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

### Owner history

owner instary	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CONTRACTOR CONT	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NE UK
Plate since	
Current registration	IK UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-26
Last registration	2024-04-02
Complete history	See info



Registration #1	2007-03-26	6 mi
Registration #2	2010-03-08	29.568 mi
Registration #3	2010-03-09	29.568 mi
Registration #4	2011-03-31	37.917 mi
Registration #5	2012-03-05	43.275 mi
Registration #6	2012-03-06	43.279 mi
Registration #7	2013-03-14	49.466 mi
Registration #8	2014-01-30	55.945 mi
Registration #9	2015-02-19	60.733 mi
Registration #10	2015-02-19	60.733 mi
Registration #11	2016-02-02	66.692 mi
	2217 22 22	74.712!
Registration #12	2017-03-20	74.713 mi
Registration #12 Registration #13	2017-03-20	74.713 mi
-		74.713 mi
Registration #13		74.713 mi
Registration #13 Registration #14		74.713 MI
Registration #13 Registration #14 Registration #15		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		74.713 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		74.713 mi

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1205 kg
Max. allowed weight	1775 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15

Number of axles 2

**Engine number** D019345