





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T3 INSCRIPTION
Colour	Blue
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	250 Nm at 1.700 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2022-03-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2022-02-14

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-23
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #5		2024-01-15 15:31
MOT test	number	642337764781
Result		✓ Passed
Next expi	ry date	2025-01-23
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2024-01-15 09:08
MOT test number	204427066366
Result	X Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2023-01-24 13:31
MOT test number	518802939371
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

Advice

SM68YZR report date: 2024-03-29

✓ Passed

MOT #2 2023-01-24 12:03

MOT test number 808859274324

Result X Failed

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #1 2021-11-11 13:53

MOT test number 298927125829

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-12-23
Last registration	2024-01-15
Complete history	See info



Registration #1	2018-12-23	9 mi
Registration #2	2021-11-11	25.231 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



SM68YZR report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1460 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine number2715067