



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Black
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-21
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-21
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	31
Total items failed	3

## MOT #15 2023-09-22 07:24

MOT test number 569263115721

Result ✓ Passed

Next expiry date 2024-09-21

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Sub-frame is corroded but structural rigidity is not significantly reduced front and rear (6.1.1 (c) (i))

## MOT #14 2023-09-12 10:13

MOT test number 850980797348

Result ✗ Failed

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MAJOR** Battery insecure and likely to fall from carrier (4.13 (a) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Sub-frame is corroded but structural rigidity is not significantly reduced front and rear (6.1.1 (c) (i))

## MOT #13 2021-01-13 09:02

MOT test number 490745087747

Result ✓ Passed

**MOT #12** 2020-01-07 14:36**MOT test number** 683137412148**Result** ✓ Passed**MOT #11** 2019-12-17 12:44**MOT test number** 942366495213**Result** ✗ Failed**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Rear Brake cable guide defective and affecting operation not connected (1.1.15 (d))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Pass with rectification** Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))**MAJOR** Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2019-01-04 09:40**MOT test number** 731571389907**Result** ✓ Passed

**MOT #9** 2018-12-31 10:51**MOT test number** 525310672261**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Rear brakepads heat damage**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (D)bushes both (5.3.4 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #8** 2018-01-13 09:31**MOT test number** 685628019841**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 225/50/17 (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2018-01-13 09:31**MOT test number** 132647053687**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit 225/50/17 (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-01-11 10:25**MOT test number** 388476458579**Result** ✓ Passed**MOT #5** 2016-01-12 14:13**MOT test number** 639920396887**Result** ✓ Passed**MOT #4** 2015-01-06 12:40**MOT test number** 179176205482**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #3** 2014-01-15 10:16**MOT test number** 126685314053**Result** ✓ Passed**MOT #2** 2013-06-28 14:22**MOT test number** 905549673149**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12013-06-28 11:23

MOT test number345119773165

Result

Failed

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:  
31 January 2024

✓

MOT

Expires:  
21 September 2024

Tax status	Expired at 31 January 2024
Days left	90 days too late
MOT expiry date	21 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-06
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2010-05-06	11 mi
Registration #2	2013-06-28	37.596 mi
Registration #3	2013-06-28	37.596 mi
Registration #4	2014-01-15	43.199 mi
Registration #5	2015-01-06	61.701 mi
Registration #6	2016-01-12	79.785 mi
Registration #7	2017-01-11	92.303 mi
Registration #8	2018-01-13	99.806 mi
Registration #9	2018-01-13	99.806 mi
Registration #10	2019-01-22	101.317 mi
Registration #11	2019-01-22	101.317 mi
Registration #12	2019-01-22	101.317 mi
Registration #13	2019-01-22	101.317 mi
Registration #14	2019-01-22	101.317 mi
Registration #15	2019-01-22	101.317 mi
Registration #16	2019-01-22	101.317 mi
Registration #17	2019-01-22	101.317 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1462 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	R20A31250972