



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-11-20
Pictures	31
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-09-08
Pictures	31
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-01-24
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	19
Total items failed	11

MOT #20	2024-01-23 16:24
MOT test number	801247660376
Result	✓ Passed
Next expiry date	2025-01-24
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #19	2024-01-23 11:27
MOT test number	772340925935
Result	✗ Failed
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #18	2023-01-18 14:59
MOT test number	880315693830
Result	✓ Passed
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Exhaust mounting defective above rear axle (6.1.2 (a))

**MOT #17**

2023-01-18 12:28

MOT test number

562141002373

Result**✗ Failed****Fail**

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Rear Exhaust mounting defective above rear axle (6.1.2 (a))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16

2022-01-25 09:54

MOT test number

442381239761

Result**✓ Passed****MOT #15**

2022-01-19 10:00

MOT test number

137065763314

Result**✗ Failed****Fail**

Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail

Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #14

2021-03-15 12:32

MOT test number

462231001191

Result**✓ Passed**

**MOT #13** 2020-03-06 12:05**MOT test number** 908197614199**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-02-28 12:05**MOT test number** 207367519325**Result** ✓ Passed**MOT #11** 2018-03-08 10:07**MOT test number** 742587997767**Result** ✓ Passed**MOT #10** 2017-03-16 14:52**MOT test number** 452484699524**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Upper Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2016-03-04 10:31**MOT test number** 993478300128**Result** ✓ Passed**MOT #8** 2015-02-20 14:04**MOT test number** 766821355094**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-02-18 12:30**MOT test number** 875799245024**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-03-05 12:26**MOT test number** 655084664033**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Both rear tyres starting to wear uneven around inner shoulders.**MOT #5** 2013-02-15 11:08**MOT test number** 517746943000**Result** ✓ Passed**MOT #4** 2013-02-15 11:08**MOT test number** 545866543057**Result** ✗ Failed**Pass with rectification** Centre Rear registration plate dirty (6.3.1d)**Pass with rectification** Centre Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2012-02-29 15:18**MOT test number** 305530162023**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2011-02-28 14:27
MOT test number	379769251094
Result	✓ Passed

MOT #1	2011-02-28 14:27
MOT test number	355589051021
Result	✗ Failed

Pass with rectification

 Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-05
Last registration	2024-01-23
Complete history	See info



Registration #1	2008-03-05	28 mi
Registration #2	2011-02-28	58.624 mi
Registration #3	2012-02-29	69.675 mi
Registration #4	2013-02-15	80.873 mi
Registration #5	2014-03-05	91.897 mi
Registration #6	2015-02-18	99.914 mi
Registration #7	2015-02-20	99.979 mi
Registration #8	2016-03-04	114.260 mi
Registration #9	2017-03-16	130.092 mi
Registration #10	2018-03-08	144.429 mi
Registration #11	2019-02-28	159.337 mi
Registration #12	2020-02-28	174.245 mi
Registration #13	2021-02-28	189.153 mi
Registration #14	2022-02-28	204.061 mi
Registration #15	2023-02-28	218.969 mi
Registration #16	2024-01-23	233.877 mi
Registration #17	2024-01-23	233.877 mi
Registration #18	2024-01-23	233.877 mi
Registration #19	2024-01-23	233.877 mi
Registration #20	2024-01-23	233.877 mi
Registration #21	2024-01-23	233.877 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100