



report date: 2024-03-28

General information

Make	NISSAN
Model	PRIMERA TD SE
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	137 BHP
Max. torque	314 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-08
Pictures	3
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #25** 2022-06-18 16:46**MOT test number** 769233493088**Result** ✓ Passed**Next expiry date** 2023-06-17

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced Under body and multiple suspension components corroded but not seriously effecting its strength causing a sharp edge or projection (6.1.1 (c) (i))

MOT #24 2021-06-03 14:07**MOT test number** 351665890795**Result** ✓ Passed

Advice Rear axle corroded

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice N/s and o/s inner sills corroded

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #23 2021-06-01 11:11**MOT test number** 771869325754**Result** ✗ Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Headlamp light source and lamp not compatible both (4.1.4 (c))

Advice Rear axle corroded

Fail Exhaust has a major leak of exhaust gases back box (6.1.2 (a))

Fail Headlamp light intensity severely reduced both (4.1.4 (a))

Advice N/s and o/s inner sills corroded

Fail Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22** 2020-05-28 11:52**MOT test number** 321108923517**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both headlamp lenses deteriorated

MOT #21 2020-05-28 11:52**MOT test number** 948615643185**Result** ✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Both headlamp lenses deteriorated

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #20 2019-06-04 15:14**MOT test number** 387396658869**Result** ✓ Passed

**MOT #19** 2019-06-04 12:29**MOT test number** 526720618025**Result** ✗ Failed

- Fail** Power steering malfunctioning (2.1.5 (a))
- Fail** Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Front Direction indicator incorrect colour both white (4.4.3 (a))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Power steering component leaking rack boots (2.1.5 (a))
- Fail** Front Suspension arm pin or bush excessively worn both (5.3.4 (a) (i))
- Fail** Front Side repeater incorrect colour both sides white (4.4.3 (a))

MOT #18 2018-06-06 15:25**MOT test number** 800508839832**Result** ✓ Passed**MOT #17** 2018-06-06 12:03**MOT test number** 846454372656**Result** ✗ Failed

- Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #16** 2017-05-15 16:13**MOT test number** 786748015181**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** O/s/r tyre perished**MOT #15** 2017-05-03 10:25**MOT test number** 738556252395**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** O/s/r tyre perished**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #14** 2016-06-02 07:08**MOT test number** 578802257251**Result** ✓ Passed**MOT #13** 2016-06-02 07:08**MOT test number** 645265275806**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #12** 2015-06-04 10:59**MOT test number** 915805155151**Result** ✓ Passed**Notice** O/s/f tyre perished**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #11** 2015-06-04 10:59**MOT test number** 965715855193**Result** ✗ Failed**Notice** O/s/f tyre perished**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #10** 2014-06-06 11:08**MOT test number** 257397254486**Result** ✓ Passed**Notice** All four tyres worn on edges**MOT #9** 2014-06-06 11:08**MOT test number** 147257854120**Result** ✗ Failed**Notice** All four tyres worn on edges**Pass with rectification** Battery insecure (1.9.1)

**MOT #8** 2013-08-01 12:49**MOT test number** 336593913246**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #7** 2013-07-31 12:51**MOT test number** 129002813242**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #6** 2012-06-19 14:01**MOT test number** 136251072115**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #5** 2011-03-23 11:58**MOT test number** 879972881029**Result** ✓ Passed**MOT #4** 2009-10-24 11:30**MOT test number** 531367699258**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Oil leak

**MOT #3** 2009-10-23 15:25**MOT test number** 140726999261**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Oil leak**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-09-12 14:19**MOT test number** 444636558290**Result** ✓ Passed**MOT #1** 2007-09-11 12:23**MOT test number** 334654557442**Result** ✓ Passed**Advice** Nearside Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-10-01
Last registration	2022-06-18
Complete history	See info



Registration #1	2004-10-01	20 mi
Registration #2	2007-09-11	37.722 mi
Registration #3	2008-09-12	8.237 mi
Registration #4	2009-10-23	14.334 mi
Registration #5	2009-10-24	14.352 mi
Registration #6	2011-03-23	25.683 mi
Registration #7	2012-06-19	32.209 mi
Registration #8	2013-07-31	386.969 mi
Registration #9	2013-08-01	38.696 mi
Registration #10	2014-06-06	44.586 mi
Registration #11	2015-06-04	51.948 mi
Registration #12	2016-06-02	57.255 mi
Registration #13	2016-06-02	57.255 mi
Registration #14	2016-06-02	57.255 mi
Registration #15	2016-06-02	57.255 mi
Registration #16	2016-06-02	57.255 mi
Registration #17	2016-06-02	57.255 mi
Registration #18	2016-06-02	57.255 mi
Registration #19	2016-06-02	57.255 mi
Registration #20	2016-06-02	57.255 mi
Registration #21	2016-06-02	57.255 mi
Registration #22	2016-06-02	57.255 mi
Registration #23	2016-06-02	57.255 mi
Registration #24	2016-06-02	57.255 mi
Registration #25	2016-06-02	57.255 mi



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1482 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1497 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	787342