





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Black
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 1


Date 2021-12-02

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



RV62LVW
report date: 2024-03-29

MOT history

MOT expiry date	2024-11-25
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #10	2023-11-23 10:07
MOT test number	644779685882
Result	✓ Passed
Next expiry date	2024-11-25
Advice Front Tyre worn close to legal limit/worn on edge Nearside and Offside (5.2.3 (e))	

MOT #9	2022-11-23 11:08
MOT test number	520256780812
Result	✓ Passed
Minor Hazard warning switch faulty (4.4.2 (a) (i))	

MOT #8	2021-11-19 10:38
MOT test number	211805858138
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #7** 2020-11-26 15:25

MOT test number 996435591445

**Result** ✓ Passed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing bush (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing bush (5.3.4 (a) (i))

MOT #6 2020-11-26 15:25

MOT test number 609196966413

Result X Failed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing bush (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing bush (5.3.4 (a) (i))

**Pass with rectification** Exhaust system insecure rear bracket reattached. (6.1.2 (a))

**MOT #5** 2019-04-18 08:20

MOT test number 276768890391

Result \( \sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**Advice** Corrosion in general exhaust system

**Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #2

**MOT test number** 

**RV62LVW** 

report date: 2024-03-29

2016-10-27 09:36

778502434110

MOT #4	2017-10-02 14:49
MOT test number	830419132081
Result	✓ Passed
MOT #3	2017-09-29 12:40
MOT test number	146315783525
Result	<b>×</b> Failed
Fail Hazard warning switch faulty (1.4.B.1d)	

Result	<b>✓</b> Passed
MOT #1	2015-09-28 08:23
MOT test number	306870647012
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check





Expires: 25 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	25 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

**RV62LVW** 

report date: 2024-03-29

More info >

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT
********		
***************************************		
***********		
********		
*************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK MIN	
Plate since		
Current registration	NIK SIE	T T T

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-30
Last registration	2023-11-23
Complete history	See info



Registration #1	2012-09-30	15 mi
Registration #2	2015-09-28	27.009 mi
Registration #3	2016-10-27	28.172 mi
Registration #4	2017-09-29	31.319 mi
Registration #5	2017-10-02	31.332 mi
Registration #6	2019-04-18	47.314 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

### Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 12/12