




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA DIAMOND CDTI S/S
Colour	Grey
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 3

Date	2021-08-19
Pictures	60
Listing price	View report



source: [yesauto.com](#)

Entry 2

Date	2021-07-28
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-07-25
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-12
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	38
Total items failed	7

MOT #11	2023-10-13 12:20
---------	------------------

MOT test number	452477472381
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-12
------------------	------------

Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2023-10-09 12:55

MOT test number

249022880418

Result**✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2022-09-05 12:31

MOT test number

888891966087

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8

2022-09-05 10:21

MOT test number

584700833088

Result

✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2021-08-24 14:37**MOT test number** 376602394150**Result** ✓ Passed**MOT #6** 2021-08-24 14:37**MOT test number** 129990631231**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2020-07-25 08:18**MOT test number** 184319711610**Result** ✓ Passed**MOT #4** 2019-07-27 08:33**MOT test number** 819800539438**Result** ✓ Passed**MOT #3** 2018-07-21 07:43**MOT test number** 291871150514**Result** ✓ Passed**MOT #2** 2017-07-22 09:02**MOT test number** 124221279161**Result** ✓ Passed**MOT #1** 2017-07-22 09:02**MOT test number** 544756602818**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-24
Last registration	2023-10-13
Complete history	See info



Registration #1	2014-09-24	24 mi
Registration #2	2017-07-22	20.977 mi
Registration #3	2017-07-22	20.977 mi
Registration #4	2018-07-21	29.940 mi
Registration #5	2019-07-27	32.758 mi
Registration #6	2020-07-25	40.499 mi
Registration #7	2020-07-25	20.977 mi
Registration #8	2020-07-25	20.977 mi
Registration #9	2020-07-25	20.977 mi
Registration #10	2020-07-25	20.977 mi
Registration #11	2020-07-25	20.977 mi
Registration #12	2020-07-25	20.977 mi
Registration #13	2020-07-25	20.977 mi
Registration #14	2020-07-25	20.977 mi
Registration #15	2020-07-25	20.977 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2479 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 342650K LNQ