



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 2

Date	2021-12-18
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-17
Pictures	24
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2022-12-08 13:44
MOT test number	375975171083
Result	✓ Passed
Next expiry date	2023-12-07
Advice Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	

MOT #18	2022-12-08 11:04
MOT test number	941925484929
Result	✗ Failed
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Fail Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))	
Fail Offside Front All direction indicators not working (4.4.1 (a) (ii))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Emissions not tested exhaust leak (8.2.1.2 (d))	
Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Fail Rear Exhaust system insecure back box (6.1.2 (a))	

MOT #17

2021-12-08 13:02

MOT test number

474068952029

Result

✓ Passed

**MOT #16** 2021-11-26 20:08**MOT test number** 676475351677**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #15** 2021-01-19 12:58**MOT test number** 851550419640**Result** ✓ Passed**MOT #14** 2021-01-19 12:58**MOT test number** 971239700110**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #13** 2020-01-17 14:22**MOT test number** 165845109142**Result** ✓ Passed**MOT #12** 2020-01-16 12:53**MOT test number** 490861045771**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))

**MOT #11** 2019-01-14 12:59**MOT test number** 927890660773**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2018-01-09 12:58**MOT test number** 822580825936**Result** ✓ Passed**Advice** O/s rear tyre light perishing to side wall**Advice** N/s side repeater pale**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2018-01-03 13:23**MOT test number** 707435782858**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** O/s rear tyre light perishing to side wall**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** N/s side repeater pale**MOT #8** 2017-01-11 13:03**MOT test number** 810026585274**Result** ✓ Passed**MOT #7** 2016-01-19 11:56**MOT test number** 701341337979**Result** ✓ Passed

**MOT #6** 2014-10-27 17:13**MOT test number** 856780404358**Result** ✓ Passed**MOT #5** 2014-10-27 17:13**MOT test number** 107200704328**Result** ✗ Failed**Pass with rectification** Rear Exhaust system not adequately supported (7.1.1)**MOT #4** 2013-09-03 09:31**MOT test number** 286576743204**Result** ✓ Passed**MOT #3** 2012-04-04 15:21**MOT test number** 177875092491**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-21 11:22**MOT test number** 503875050377**Result** ✓ Passed**MOT #1** 2009-09-24 12:16**MOT test number** 830297469257**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LV56LKJ
Plate since	2019-09-28
Current registration	LV56LKJ
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-30
Last registration	2022-12-08
Complete history	See info



Registration #1	2006-09-30	24 mi
Registration #2	2009-09-24	11.542 mi
Registration #3	2010-12-21	12.826 mi
Registration #4	2012-04-04	18.264 mi
Registration #5	2013-09-03	33.390 mi
Registration #6	2014-10-27	41.035 mi
Registration #7	2016-01-19	48.357 mi
Registration #8	2017-01-11	56.846 mi
Registration #9	2018-01-03	64.492 mi
Registration #10	2018-01-09	64.492 mi
Registration #11	2019-01-14	72.717 mi
Registration #12	2019-01-14	72.717 mi
Registration #13	2019-01-14	72.717 mi
Registration #14	2019-01-14	72.717 mi
Registration #15	2019-01-14	72.717 mi
Registration #16	2019-01-14	72.717 mi
Registration #17	2019-01-14	72.717 mi
Registration #18	2019-01-14	72.717 mi
Registration #19	2019-01-14	72.717 mi
Registration #20	2019-01-14	72.717 mi
Registration #21	2019-01-14	72.717 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3097262