






report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L2H2 HDI
Colour	White
Year of manufacture	2015
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	1



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-25

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-16
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	27
Total items failed	13


MOT #10	2023-08-17 12:31
MOT test number	331255575709
Result	✓ Passed
Next expiry date	2024-08-16
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1	
Advice Power steering pipe/hose has slight seepage at steering rack (2.1.5 (a))	
Advice Wheel/tyre protruding beyond wheel arch all	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/13



NK65OGJ

report date: 2024-03-28



MOT #8	2022-07-22 07:30
MOT test number	804210199004
Result	✓ Passed
Advice Power steering pipe/hose has slight seepage (2.1.5 (a))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in Rear bush (5.3.4 (a) (i))	excessive movement
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lam (4.7.1 (b) (i))	ps or light sources
Advice Front Service brake requirements only just met. It would appear that the badjustment or repair (1.2.1 (c))	oraking system requires
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in Rear bush (5.3.4 (a) (i))	n excessive movement

CarCheck.co.uk page 4/13



MOT #7 2022-07-21 09:58

MOT test number 203172595066

Result X Failed

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #6 2021-07-20 11:03

MOT test number 260343635189

Result ✓ Passed

MOT #5 2020-07-09 10:58

MOT test number 598504774926

Result \(\sqrt{Passed} \)

Advice Nearside Rear tyre worn on edge

Advice Offside Front tyre perishing on outer sidewall

CarCheck.co.uk page 5/13



MOT #4 2020-07-08 11:13

MOT test number 100981950667

Result × Failed

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear tyre worn on edge

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Offside Front tyre perishing on outer sidewall

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #3 2019-08-05 17:25

MOT test number 600812581298

Result \(\sqrt{Passed} \)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2018-10-02 14:52

MOT test number 521972647896

Result

Passed

MOT #1 2018-09-25 10:59

MOT test number 506339957384

Result × Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Coolant leak

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-30
Last registration	2023-08-17
Complete history	See info



Registration #1	2015-09-30	27 mi
Registration #2	2018-09-25	37.463 mi
Registration #3	2018-10-02	37.463 mi
Registration #4	2019-08-05	47.887 mi
Registration #5	2020-07-08	53.023 mi
Registration #6	2020-07-09	53.025 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2050 mm
Height	2522 mm
Length	5413 mm
Wheel base	3450 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	TRJA0810982

CarCheck.co.uk page 13/13