



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA SXI 16V TWINPORT
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg





Internet history

Entry 1

Date	2021-07-04
Pictures	29
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #14	2021-01-15 12:39
MOT test number	823333398639
Result	✓ Passed
Next expiry date	2022-01-14
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Steering rack has slight free play detected at steering wheel both rack arms (2.3 (a) (i))

MOT #13	2021-01-12 13:26
MOT test number	422714892962
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Steering rack has slight free play detected at steering wheel both rack arms (2.3 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2019-07-30 13:23
MOT test number	795819577695
Result	✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11	2018-05-29 13:36
MOT test number	503779788895
Result	✓ Passed

**MOT #10** 2018-05-29 13:36**MOT test number** 829124822161**Result** ✗ Failed**Pass with rectification**

Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #9 2017-06-26 16:15**MOT test number** 861121324813**Result** ✓ Passed**Advice** O/s/f cv boot slight leak**Advice** Slight play in both front steering rack ends**Advice** Front pads and discs worn**Advice** O/s/f antiroll bar link boot slight damage**MOT #8** 2016-06-30 10:40**MOT test number** 816569661882**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-09-01 15:57**MOT test number** 866414145216**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2014-03-15 08:37**MOT test number** 575214074010**Result** ✓ Passed**Notice** Fuel filter corroding**Notice** Slight oil leak**MOT #5** 2014-03-13 12:48**MOT test number** 169002574433**Result** ✗ Failed**Notice** Slight oil leak**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Fuel filter corroding**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #4** 2013-03-13 14:23**MOT test number** 116432273016**Result** ✓ Passed**MOT #3** 2012-03-24 09:23**MOT test number** 778814582073**Result** ✓ Passed**MOT #2** 2011-03-16 10:36**MOT test number** 717335971070**Result** ✓ Passed**Notice** Front discs slightly scored



MOT #1	2011-03-16 10:36
MOT test number	629075171060
Result	✗ Failed
Pass with rectification	Offside Rear fog lamp not working (1.3.2b)
Notice	Front discs slightly scored
Pass with rectification	Registration plate lamp not working (1.1.C.1d)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DF08VLM
Plate since	2019-06-29
Current registration	 DF08VLM
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-03-28
Last registration	2021-01-15
Complete history	See info



Registration #1	2008-03-28	7 mi
Registration #2	2011-03-16	19.531 mi
Registration #3	2012-03-24	23.989 mi
Registration #4	2013-03-13	29.154 mi
Registration #5	2014-03-13	34.345 mi
Registration #6	2014-03-15	34.345 mi
Registration #7	2015-09-01	41.857 mi
Registration #8	2016-06-30	43.028 mi
Registration #9	2016-06-30	43.028 mi
Registration #10	2016-06-30	43.028 mi
Registration #11	2016-06-30	43.028 mi
Registration #12	2016-06-30	43.028 mi
Registration #13	2016-06-30	43.028 mi
Registration #14	2016-06-30	43.028 mi
Registration #15	2016-06-30	43.028 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1753 mm
Height	1413 mm
Length	4288 mm
Wheel base	2614 mm
Kerb weight	1180 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	19PU0404