



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 SPORT
Colour	Black
Year of manufacture	2005
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.700 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-25
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	41
Total items failed	24

MOT #22	2023-10-13 15:12
MOT test number	338399538441
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #21	2022-10-10 13:58
MOT test number	645927282520
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Track rod end ball joint has slight play Nearside and Offside (2.1.3 (b) (i))
Advice	Front Shock absorbers has a reduced damping effect Nearside and Offside (5.3.2 (d))
Advice	Rear Shock absorbers has a slightly worn bush Nearside and Offside (5.3.2 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2021-10-20 12:03
MOT test number	593234739566
Result	✓ Passed

**MOT #19** 2021-09-27 14:14**MOT test number** 513035610583**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear engine mounting bush worn**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18** 2020-09-28 14:13**MOT test number** 785124960217**Result** ✓ Passed**MOT #17** 2019-09-24 13:22**MOT test number** 234871753857**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #16** 2017-10-23 11:04**MOT test number** 426571422735**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #15** 2017-10-19 10:57**MOT test number** 271993415588**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter split (2.2.D.2d)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #14**

2016-10-11 15:18

MOT test number

239578348357

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement bottom (2.4.G.2)

Advice Nearside Front Drag link end ball joint has slight play inner (2.2.B.1f)

MOT #13

2016-10-08 11:58

MOT test number

390410245240

Result

✗ Failed

Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Offside Front Steering rack gaiter split (2.2.D.2d)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement bottom (2.4.G.2)

Advice Nearside Front Drag link end ball joint has slight play inner (2.2.B.1f)

Fail Nearside Front Steering rack gaiter insecure (2.2.D.2d)

Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #12

2015-10-12 14:53

MOT test number

946505333341

Result

✓ Passed

Advice Nearside Power steering component(s) has slight seepage from a component rack, light misting of oil (2.3.3b)



MOT #11	2015-10-10 10:06
MOT test number	355051264803
Result	✗ Failed
Fail	Nearside front brake excessively fluctuating (3.7.B.3)
Fail	Nearside Steering rack gaiter split (2.2.D.2d)
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Offside front brake excessively fluctuating (3.7.B.3)
Advice	Nearside Power steering component(s) has slight seepage from a component rack, light misting of oil (2.3.3b)

MOT #10	2013-10-10 16:27
MOT test number	308973083249
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Nearside rear and offside front tyre has splits in the tread but not deep enough to reach the ply or cords
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2013-09-28 12:07**MOT test number** 928761973206**Result** ✗ Failed

- Notice** Nearside rear tyre has splits on the side wall not deep enough to reach ply or cords
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)
- Notice** Offside front tyre has splits on tread but not deep enough to reach the ply or cords
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2012-09-10 11:36**MOT test number** 847214452218**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-09-13 15:15**MOT test number** 796086751298**Result** ✓ Passed

- Notice** Nearside rear tyre (175 65 14t) cracked and worn on outer side wall

**MOT #6** 2011-09-13 09:52**MOT test number** 669976851289**Result** ✗ Failed**Fail** Front Exhaust has part of the system excessively deteriorated (7.1.1a)**Notice** Nearside rear tyre (175 65 14t) cracked and worn on outer side wall**Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Horn not working (1.6.2a)**MOT #5** 2010-09-18 10:24**MOT test number** 591051560206**Result** ✓ Passed**Notice** Front exhaust/gearbox mounting deteriorated**MOT #4** 2010-09-17 11:25**MOT test number** 503260460271**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Offside rear brake binding (3.7.B.1)**Fail** Nearside Drag link end ball joint has excessive play (2.2.B.1f)**Notice** Front exhaust/gearbox mounting deteriorated**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Brake hydraulic reservoir cap missing (3.6.G.1a)**Fail** Brakes imbalanced across an axle (3.7.B.5b)

**MOT #3** 2009-09-16 15:54**MOT test number** 504639759264**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)

MOT #2 2009-09-16 11:09**MOT test number** 521849259285**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Exhaust system not adequately supported (7.1.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2008-09-18 11:42**MOT test number** 781952068262**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	NU55UNM
Plate since	2019-09-28
Current registration	NU55UNM
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-29
Last registration	2023-10-13
Complete history	See info



Registration #1	2005-09-29	24 mi
Registration #2	2008-09-18	27.829 mi
Registration #3	2009-09-16	36.830 mi
Registration #4	2009-09-16	36.830 mi
Registration #5	2010-09-17	43.785 mi
Registration #6	2010-09-18	43.786 mi
Registration #7	2011-09-13	51.346 mi
Registration #8	2011-09-13	51.346 mi
Registration #9	2012-09-10	56.412 mi
Registration #10	2013-09-28	57.891 mi
Registration #11	2013-10-10	57.891 mi
Registration #12	2015-10-10	63.543 mi
Registration #13	2016-09-29	65.557 mi
Registration #14	2016-09-29	65.557 mi
Registration #15	2016-09-29	65.557 mi
Registration #16	2016-09-29	65.557 mi
Registration #17	2016-09-29	65.557 mi
Registration #18	2016-09-29	65.557 mi
Registration #19	2016-09-29	65.557 mi
Registration #20	2016-09-29	65.557 mi
Registration #21	2016-09-29	65.557 mi
Registration #22	2016-09-29	65.557 mi
Registration #23	2016-09-29	65.557 mi
Registration #24	2016-09-29	65.557 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FP7N4782768