





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date	2024-02-12
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2021-08-10	
Pictures	23	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-26
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #13	2024-02-27 11:10
MOT test number	546160654825
Result	✓ Passed
Next expiry date	2025-02-26

MOT #12	2024-02-22 16:32
MOT test number	963420012159
Result	X Failed
Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))	

MOT #11		2023-08-01 08:23
MOT test	number	515054691983
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Valve stem slightly misaligned (5.2.3 (j))	
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exces	ssive movement
(5.3.4 (a) (
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excess	ive movement (5.3.4

CarCheck.co.uk page 3/12



SJ620BP

report date: 2024-03-28

MOT test number

Result

Advice Advise rear beam axle corroded

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9 2022-07-25 10:48 **MOT** test number 697193809785 Result × Failed Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Advice Advise rear beam axle corroded Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

 MOT #8
 2021-08-09 06:51

 MOT test number
 132909150750

 Result
 ✓ Passed

MOT test number

Result

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 4/12



MOT #1

Result

MOT test number

SJ620BP report date: 2024-03-28

2015-09-22 13:13 993755666840

✓ Passed

MOT #6	2021-01-09 09:48
MOT test number	231740051364
Result	✓ Passed
MOT #5	2020-01-11 09:46
MOT test number	392186644915
Result	✓ Passed
MOT #4	2019-01-09 11:17
MOT test number	212744831677
Result	✓ Passed
MOT #3	2019-01-08 14:50
MOT test number	604311167447
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MOT #2	2018-01-16 13:10
MOT test number	652930139479
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



SJ620BP

report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



SJ620BP

More info >

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. factor scincore

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-24
Last registration	2024-02-27
Complete history	See info



Registration #1	2012-09-24	16 mi
Registration #2	2015-09-22	15.935 mi
Registration #3	2018-01-16	17.098 mi
Registration #4	2019-01-08	28.596 mi
Registration #5	2019-01-09	28.596 mi
Registration #6	2020-01-11	42.274 mi
Registration #7	2021-01-09	56.866 mi
Registration #8	2021-08-09	64.475 mi
Registration #9		11.777 es
Registration #9 Registration #10		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #10		11,777 es
Registration #10 Registration #11		11,777 est 11,777 est 11,777 est 11,777 est
Registration #10 Registration #11 Registration #12		10,000 ess 10,000 ess 10,000 ess 10,000 ess 10,000 ess
Registration #10 Registration #11 Registration #12 Registration #13		10,000 eac 10,000 eac 10,000 eac 10,000 eac 10,000 eac 10,000 eac

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 12/12