





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|----------------------------|
| Model | HI-ACE 280 SWB P/V D-4D 95 |
| Colour | Blue |
| Year of manufacture | 2007 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 94 BHP |
|-----------------|---------------------|
| Max. torque | 230 Nm at 2.800 rpm |
| Engine capacity | 2.494 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| | |







MOT history

| MOT expiry date | 2021-08-17 |
|--------------------|------------|
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 10 |
| Total items failed | 8 |

| MOT #14 | 2020-08-18 15:33 | |
|--|------------------|--|
| MOT test number | 734149105718 | |
| Result | ✓ Passed | |
| Next expiry date | 2021-08-17 | |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material rusty near ferrell (1.1.11 (c)) | | |

| MOT #13 | 2019-11-05 15:58 |
|---|-----------------------------|
| MOT test number | 194022790815 |
| Result | ✓ Passed |
| Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in (a) (i)) | n excessive movement (5.3.4 |

| MOT #12 | 2018-10-31 16:13 |
|--|------------------|
| MOT test number | 814845360410 |
| Result | Passed |
| Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement | |

(5.3.4 (a) (i))

| MOT #11 | 2017-11-03 12:03 |
|---|------------------|
| MOT test number | 340875575767 |
| Result | ✓ Passed |
| Advice Rear Brake pipe slightly corroded (3.6.B.2c) | |





| MOT # | 10 | 2017-11-01 11:01 |
|--------|--|------------------|
| MOT te | est number | 686745269058 |
| Result | | 🗙 Failed |
| Advid | Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Fail | Nearside Rear Registration plate lamp not working (1.1.C.1d) | |
| Fail | Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2) | |
| Fail | Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f) | |
| Fail | Offside Rear Registration plate lamp not working (1.1.C.1d) | |
| Fail | Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2) | |

| МОТ #9 | 2016-10-22 10:37 |
|---|------------------|
| MOT test number | 410946203809 |
| Result | ✓ Passed |
| Advice Clutch pedal Rubber missing. | |
| Advice Timing belt warning illuminated. | |

| MOT #8 | | 2016-10-22 10:37 |
|-------------------------|--|------------------|
| MOT test number | | 985792237172 |
| Result | | 🗙 Failed |
| Advice Clutch pedal Rul | bber missing. | |
| Pass with rectification | Nearside Stop lamp not working (1.2.1b) | |
| Advice Timing belt warr | ning illuminated. | |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) | |

| MOT #7 | 2015-10-22 08:45 |
|-----------------|------------------|
| MOT test number | 292069314125 |
| Result | ✓ Passed |





| MOT #6 | 2014-11-03 11:43 |
|---|------------------|
| MOT test number | 636627804329 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2014-11-03 11:43 |
| MOT test number | 557587404380 |
| Result | 🗙 Failed |
| Pass with rectification Nearside Rear position lamp(s) not working (1.1.A.3b) | |
| | |
| MOT #4 | 2013-10-26 09:47 |
| MOT test number | 188879493252 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2012-10-22 16:49 |
| MOT test number | 497796092207 |
| Result | Passed |
| | |
| MOT #2 | 2011-10-22 09:34 |
| MOT test number | 819915391244 |
| Result | ✓ Passed |
| Advice Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2) | |
| | |
| MOT #1 | 2010-10-21 14:08 |
| MOT test number | 632664290286 |
| Result | ✓ Passed |





Tax & MOT check

| X Untaxed | Х MOT |
|-------------------------------|----------------------------|
| Tax expired: 31 March 2021 | Expired: 17 August 2021 |
| Tax status | Expired at 31 March 2021 |
| Days left | 1124 days too late |
| MOT expiry date | 17 August 2021 |
| Full MOT history | See MOT history |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FERRE |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| Damage 2 | E Stand |
| Date | * |
| Category | AMP |
| Туре | |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6 10.200 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 200 |





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2007-10-18 |
| Last registration | 2020-08-18 |
| Complete history | See info |



| Registration #1 | 2007-10-18 | 28 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2010-10-21 | 36.440 mi |
| Registration #3 | 2011-10-22 | 51.364 mi |
| Registration #4 | 2012-10-22 | 71.899 mi |
| Registration #5 | 2013-10-26 | 83.644 mi |
| Registration #6 | 2014-11-03 | 91.821 mi |
| Registration #7 | 2015-10-22 | 99.955 mi |
| Registration #8 | | 11.117 esi |
| | | |
| Registration #9 | | 10.207 mi |
| Registration #9 Registration #10 | | 00.000 est |
| - | | 01,000 est 01,000 est 01,000 est |
| Registration #10 | | 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #10 Registration #11 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |





Car features

| S0225 | Air conditionin |
|--------|-----------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Dimensions & weight

Number of axles

Engine number

| Width | 1800 mm |
|------------------------|------------------|
| Height | 2000 mm |
| Length | 4795 mm |
| Wheel base | 2500 mm |
| Kerb weight | 1750 kg |
| Max. allowed weight | 2800 kg |
| Additional information | |
| Fuel tank capacity | 75 I |
| Fuel delivery | Direct Injection |
| Number of seats | 3 |

2

2KD1700522