



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 D SE AWD
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 2


Date	2022-01-25
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-10-27
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-01
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #17	2024-02-20 15:10
MOT test number	676671725133
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Rear Brake disc worn, but not excessively corroded / lipped (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively corroded / lipped (1.1.14 (a) (i))

MOT #16	2023-02-28 14:24
MOT test number	565276189634
Result	✓ Passed

MOT #15	2023-02-28 14:24
MOT test number	694839048166
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

MOT #14	2022-03-02 12:50
MOT test number	877803072712
Result	✓ Passed

**MOT #13** 2021-04-15 15:15**MOT test number** 699563550545**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-04-15 15:15**MOT test number** 485599923130**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**MOT #11** 2020-04-23 16:05**MOT test number** 797425992626**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Slight play detected in steering rack

**MOT #10**

2019-04-26 15:32

**MOT test number**

207203992664

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))**MOT #9**

2018-04-19 15:57

**MOT test number**

141114322434

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2017-04-20 17:07

**MOT test number**

352941947990

**Result**

✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2016-04-16 12:00**MOT test number** 505682204699**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-04-24 17:42**MOT test number** 136394615185**Result** ✓ Passed**Notice** Front wipers smearing screen**MOT #5** 2014-10-02 14:15**MOT test number** 697515774278**Result** ✓ Passed**MOT #4** 2013-10-09 10:33**MOT test number** 925622183228**Result** ✓ Passed**Notice** Chip in windscreen outside of zone A & zone B**MOT #3** 2013-10-09 10:33**MOT test number** 976122183258**Result** ✗ Failed**Notice** Chip in windscreen outside of zone A & zone B**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2012-10-13 12:16**MOT test number** 885407082255**Result** ✓ Passed



MOT #1	2011-10-07 14:03
MOT test number	387270281213
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
1 March 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-21
Last registration	2024-02-20
Complete history	<a href="#">See info</a>



Registration #1	2008-10-21	24 mi
Registration #2	2011-10-07	27.906 mi
Registration #3	2012-10-13	36.546 mi
Registration #4	2013-10-09	48.636 mi
Registration #5	2014-10-02	59.804 mi
Registration #6	2015-04-24	65.059 mi
Registration #7	2016-04-16	78.979 mi
Registration #8	2017-04-20	91.561 mi
Registration #9	2018-04-19	104.950 mi
Registration #10	2019-04-26	119.046 mi
Registration #11	2020-05-20	133.142 mi
Registration #12	2021-06-18	147.238 mi
Registration #13	2022-07-16	161.334 mi
Registration #14	2023-08-14	175.430 mi
Registration #15	2024-01-12	189.526 mi
Registration #16	2024-02-20	203.622 mi
Registration #17		
Registration #18		
Registration #19		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1843 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	659998