





report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-03-02
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	25
Total items failed	3

MOT #12	2023-02-20 16:06
MOT test number	137484182983
Result	✓ Passed
Next expiry date	2024-03-02
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #11 2023-02-14 13:33

MOT test number 338199696929

Result × Failed **MAJOR** Emissions unable to be completed due to oil level too low (8.2.2.2 (e)) **MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii)) **MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) **MAJOR** Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **MAJOR MAJOR** Nearside Headlamp aim unable to be tested bulb not working (4.1.2 (b)) **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Coolant level too high **MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #10 2022-03-03 12:45

MOT test number 512228165510

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2021-02-17 08:46

MOT test number 301085013593

Result

Passed

Advice Nearside Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2021-02-16 09:51 **MOT** test number 465791564630 Result × Failed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i)) **MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))

 MOT #7
 2020-01-12 11:11

 MOT test number
 867019608366

 Result
 ✓ Passed

 MOT #6
 2019-01-03 08:58

 MOT test number
 783141513001

 Result
 ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2019-01-03 08:58

MOT test number 815328784107

Result × Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm 205/65/16 (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4

MOT test number

Front Brake pad(s) wearing thin approx 75-80% worn (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #3

MOT test number

Result

Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Fail

Offside Windscreen wiper does not clear the windscreen effectively split (8.2.2)

MOT #2

MOT test number

780525442322

Result

Advice

Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

 MOT #1
 2015-12-31 10:36

 MOT test number
 699798182054

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	2 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

EO62CGF

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-31
Last registration	2023-02-20
Complete history	See info



Davistos #2	2012 01 21	22!
Registration #1	2013-01-31	22 mi
Registration #2	2015-12-31	33.754 mi
Registration #3	2017-01-23	45.018 mi
Registration #4	2018-01-13	53.572 mi
Registration #5	2018-01-30	54.246 mi
Registration #6	2019-01-03	62.075 mi
Registration #7	2019-01-03	62.075 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		0.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	******
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C036427

CarCheck.co.uk page 12/12