



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 3 ECODYNAMICS
Colour	Blue
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





MOT history

MOT expiry date	2025-04-16
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	37
Total items failed	0

MOT #11	2024-04-17 08:44
MOT test number	845917515375
Result	✓ Passed
Next expiry date	2025-04-16

MOT #10	2023-03-01 11:06
MOT test number	937518242654
Result	✓ Passed

MOT #9	2022-11-11 14:45
MOT test number	680010435937
Result	✓ Passed
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Nail in tyre

**MOT #8** 2021-10-22 08:36**MOT test number** 768015038363**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear most bush (5.3.4 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))

MOT #7 2020-10-22 10:55**MOT test number** 695194130206**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front slight bind at wheel

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2020-10-21 12:22**MOT test number** 564436606701**Result** ✗ Failed

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front slight bind at wheel

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #5 2019-09-20 15:18**MOT test number** 189265208582**Result** ✓ Passed

Advice Stiff gear change

Advice Offside Rear Tyre slightly damaged/cracking or perishing in tread area (5.2.3 (d) (ii))

**MOT #4** 2019-09-20 09:49**MOT test number** 924570733363**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing in tread area (5.2.3 (d) (ii))
- MAJOR** Nearside Front Headlamp aim not tested (4.1.2 (b))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Stiff gear change

MOT #3 2018-05-26 10:41**MOT test number** 463886420498**Result** ✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #2** 2018-05-25 10:41**MOT test number** 170380971125**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #1** 2017-05-12 13:56**MOT test number** 250298805472**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-31
Last registration	2024-04-17
Complete history	See info



Registration #1	2014-05-31	8 mi
Registration #2	2017-05-12	28.405 mi
Registration #3	2018-05-25	43.069 mi
Registration #4	2018-05-26	43.069 mi
Registration #5	2019-09-20	68.736 mi
Registration #6	2019-09-20	68.736 mi
Registration #7	2019-09-20	68.736 mi
Registration #8	2019-09-20	68.736 mi
Registration #9	2019-09-20	68.736 mi
Registration #10	2019-09-20	68.736 mi
Registration #11	2019-09-20	68.736 mi
Registration #12	2019-09-20	68.736 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1341 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FCEH023122