



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | PEUGEOT |
| Model | 3008 BLUE HDI S/S ACTIVE |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 113 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 120 BHP |
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 68.9 mpg |
| CO2 emission | 108 g/km |
| CO2 label | B |







Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2023-02-19 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-11-24 |
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 2 |

MOT #7 2023-11-23 08:39**MOT test number** 610853768613**Result** Passed**Next expiry date** 2024-11-24

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2022-11-25 10:59**MOT test number** 788385632396**Result** Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2021-08-21 08:55**MOT test number** 189390031662**Result** Passed

**MOT #4** 2021-08-21 08:55**MOT test number** 320339722913**Result** ✗ Failed**Pass with rectification** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #3** 2020-07-24 16:12**MOT test number** 968346221252**Result** ✓ Passed**Advice** Offside Front tyre punctured**Advice** Child Seat fitted not allowing full inspection of adult belt across all 3 rear seats**MOT #2** 2020-07-24 12:56**MOT test number** 199094323888**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front tyre punctured**Advice** Child Seat fitted not allowing full inspection of adult belt across all 3 rear seats**MOT #1** 2019-06-07 08:58**MOT test number** 453144018813**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 24 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2016-09-29 |
| Last registration | 2023-11-23 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2016-09-29 | 8 mi |
| Registration #2 | 2019-06-07 | 36.078 mi |
| Registration #3 | 2020-07-24 | 46.641 mi |
| Registration #4 | 2020-07-24 | 46.641 mi |
| Registration #5 | 2021-08-21 | 49.947 mi |
| Registration #6 | 2022-05-20 | 55.277 mi |
| Registration #7 | 2022-05-20 | 55.277 mi |
| Registration #8 | 2022-05-20 | 55.277 mi |
| Registration #9 | 2023-11-23 | 55.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 86% |
| Children | 81% |
| Pedestrian | 31% |
| Safety systems | 97% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1837 mm |
| Height | 1639 mm |
| Length | 4365 mm |
| Wheel base | 2613 mm |
| Kerb weight | 1420 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|-------------|
| Number of axles | 2 |
| Engine number | JBGW0031571 |