



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 SE
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-24
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #18**

2022-01-08 15:42

**MOT test number**

121763395124

**Result****✗ Failed**

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Hazard warning lamps inoperative (4.4.1 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front inner tie rod slight play
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases box blowing and front joint next to flexi pipe (6.1.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Engine oil leak
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #17** 2021-01-02 10:50**MOT test number** 175294453257**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice** Suspension component pin or bush slightly worn (5.3.4 (a) (i))

**MOT #16** 2021-01-02 10:50**MOT test number** 341963833000**Result** ✗ Failed

- Advice** Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice** Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Pass with rectification** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2019-12-03 12:27**MOT test number** 445521807606**Result** ✓ Passed

**MOT #14** 2019-09-20 11:07**MOT test number** 410544612964**Result** ✗ Failed**Advice** Front Play in steering rack inner joint(s)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #13** 2018-09-07 14:19**MOT test number** 561979369009**Result** ✓ Passed**Advice** Play in steering rack inner joint(s) both sides**MOT #12** 2018-09-06 09:01**MOT test number** 917064663675**Result** ✗ Failed**Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

**MOT #11** 2017-09-13 14:21**MOT test number** 894882833166**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #10** 2016-09-08 09:17**MOT test number** 531784104748**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #9** 2015-09-13 13:14**MOT test number** 334318686439**Result** ✓ Passed**MOT #8** 2014-09-22 13:56**MOT test number** 907355764219**Result** ✓ Passed**MOT #7** 2013-09-11 12:28**MOT test number** 967114253295**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-09-18 11:10**MOT test number** 416122862244**Result** ✓ Passed

**MOT #5** 2011-09-23 10:34**MOT test number** 546536861231**Result** ✓ Passed**MOT #4** 2010-09-13 13:28**MOT test number** 533256250247**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-09-13 13:28**MOT test number** 584186850289**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-09-17 10:32**MOT test number** 840510469250**Result** ✓ Passed**MOT #1** 2008-10-23 16:27**MOT test number** 322217498433**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-10-28
Last registration	2022-01-08
Complete history	<a href="#">See info</a>



Registration #1	2005-10-28	14 mi
Registration #2	2008-10-23	30.855 mi
Registration #3	2009-09-17	34.595 mi
Registration #4	2010-09-13	44.073 mi
Registration #5	2011-09-23	52.209 mi
Registration #6	2012-09-18	57.839 mi
Registration #7	2013-09-11	62.688 mi
Registration #8	2014-09-22	68.059 mi
Registration #9	2015-09-13	73.009 mi
Registration #10	2016-09-08	78.388 mi
Registration #11	2017-09-08	83.767 mi
Registration #12	2018-09-08	89.146 mi
Registration #13	2019-09-08	94.525 mi
Registration #14	2020-09-08	99.904 mi
Registration #15	2021-09-08	105.283 mi
Registration #16	2022-01-08	110.662 mi
Registration #17	2022-01-08	116.041 mi
Registration #18	2022-01-08	121.420 mi
Registration #19	2022-01-08	126.799 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1049 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FE010119262