



report date: 2024-03-28

General information

Make	KIA
Model	RIO 16V
Colour	Black
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-02
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-17
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-06-16
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	36
Total items failed	8

MOT #17	2023-06-02 17:00
MOT test number	839366903850
Result	✓ Passed
Next expiry date	2024-06-16
Advice	Front Brake pipe corroded, covered in grease or other material x2 front (1.1.11 (c))

MOT #16	2023-06-02 11:57
MOT test number	627424341580
Result	✗ Failed
Advice	Front Brake pipe corroded, covered in grease or other material x2 front (1.1.11 (c))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #15	2022-06-13 14:32
MOT test number	649047797889
Result	✓ Passed

MOT #14	2021-06-16 13:34
MOT test number	765881115251
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-06-17 14:30**MOT test number** 807958181348**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened FACE (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened FACE (1.1.14 (a) (ii))**MOT #12** 2019-03-26 15:22**MOT test number** 739400274561**Result** ✓ Passed**MOT #11** 2018-04-06 08:35**MOT test number** 807476463739**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) slightly corroded Steel pipes on steering rack . (2.3.2)**MOT #10** 2018-04-06 08:35**MOT test number** 292475550739**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Power steering pipe(s) or hose(s) slightly corroded Steel pipes on steering rack . (2.3.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Power steering fluid level below minimum (2.3.1)**MOT #9** 2017-04-10 13:54**MOT test number** 569567885085**Result** ✓ Passed



MOT #8	2016-07-04 13:54
MOT test number	297944013023
Result	✓ Passed

MOT #7	2015-07-30 11:55
MOT test number	335421515427
Result	✓ Passed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Nearside rear tyre cracking in tread
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6	2015-07-30 09:07
MOT test number	785171715253
Result	✗ Failed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside rear tyre cracking in tread
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Front registration plate deteriorated (6.3.1d)

**MOT #5**

2014-07-31 10:53

**MOT test number**

306202514432

**Result**

✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4**

2014-07-31 10:53

**MOT test number**

367092614473

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2013-07-29 11:31

**MOT test number**

808930713218

**Result**

✓ Passed

**Notice** Nail in nearside front tyre**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #2	2012-07-17 14:18
MOT test number	978959092134
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2011-07-05 10:36
MOT test number	645496981134
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
16 June 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	16 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-12
Last registration	2023-06-02
Complete history	<a href="#">See info</a>



Registration #1	2008-01-12	17 mi
Registration #2	2011-07-05	23.119 mi
Registration #3	2012-07-17	33.387 mi
Registration #4	2013-07-29	44.239 mi
Registration #5	2014-07-31	54.263 mi
Registration #6	2015-07-30	59.129 mi
Registration #7	2015-07-30	59.129 mi
Registration #8	2016-07-04	63.767 mi
Registration #9	2017-04-10	69.167 mi
Registration #10	2018-04-06	72.900 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi
Registration #19	2019-06-20	75.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1079 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EE7H135778