



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AURIS DUAL VVT-I ICON
Colour	Blue
Year of manufacture	2013
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	128 Nm at 3.800 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-03-09
Pictures	3
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-08-17
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	32
Total items failed	3

MOT #10	2023-08-18 15:03
MOT test number	739728120243
Result	✓ Passed
Next expiry date	2024-08-17

MOT #9	2023-01-30 12:19
MOT test number	951478891790
Result	✓ Passed

**MOT #8**

2022-01-17 11:39

**MOT test number**

677669878396

**Result**

✓ Passed

- Advice** General corrosion at underside and at suspension components
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Slight wear at front brake discs
- Advice** Slight pitting at rear brake discs
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Front wishbones , rear bushes splitting

**MOT #7**

2021-02-02 14:23

**MOT test number**

708730051908

**Result**

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** General corrosion at underside and at suspension components
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Front wishbone rear bushes splitting
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))



MOT #6	2020-01-10 09:19
MOT test number	420312474913
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material rusty (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material rusty (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material rusty (1.1.11 (c))
Advice	Front wishbone rear bushes splitting
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Inner Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Minor	Nearside Front Windscreen wiper blade defective blade torn (3.4 (b) (i))

MOT #5	2019-01-16 15:30
MOT test number	520982015691
Result	✓ Passed
Advice	Offside front wiper blade torn
Advice	Rear brake pipes rusty
Advice	Front wishbone rear bushes splitting

**MOT #4** 2019-01-16 11:52**MOT test number** 871867638345**Result** ✗ Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread cracked to cord (5.2.3 (d) (i))

**Advice** Offside front wiper blade torn

**Advice** Rear brake pipes rusty

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread cracked to cord (5.2.3 (d) (i))

**Advice** Front wishbone rear bushes splitting

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread cracked to cord (5.2.3 (d) (i))

**MOT #3** 2018-01-25 09:39**MOT test number** 753836737926**Result** ✓ Passed

**Advice** Front wishbone rear bushes starting to split

**Advice** Slight cracking at front tyres

**Advice** Slight cracking at offside rear tyre

**MOT #2** 2017-01-20 09:14**MOT test number** 587279942551**Result** ✓ Passed**MOT #1** 2016-01-12 15:32**MOT test number** 786811622870**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-02-08
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2013-02-08	16 mi
Registration #2	2016-01-12	35.947 mi
Registration #3	2017-01-20	38.606 mi
Registration #4	2018-01-25	41.721 mi
Registration #5	2019-01-16	44.177 mi
Registration #6	2019-01-16	44.177 mi
Registration #7	2019-01-16	44.177 mi
Registration #8	2019-01-16	44.177 mi
Registration #9	2019-01-16	44.177 mi
Registration #10	2019-01-16	44.177 mi
Registration #11	2019-01-16	44.177 mi
Registration #12	2019-01-16	44.177 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1760 mm
Height	1390 mm
Length	4275 mm
Wheel base	2600 mm
Kerb weight	1235 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1NR0581876