




General information

Make	HYUNDAI
Model	I20 MPI PREMIUM SE
Colour	Grey
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	134 Nm at 3.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

**Entry 1**

Date	2021-06-14
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	15
Total items failed	4

<b>MOT #9</b>	2024-02-21 10:38
MOT test number	220908563108
Result	✓ Passed
Next expiry date	2025-03-01

<b>MOT #8</b>	2023-02-24 09:58
MOT test number	356623670424
Result	✓ Passed
<b>Minor</b>	Nearside Front Side repeater with a multiple light source up to 1/2 not functioning side repeater in mirror (4.4.1 (a) (i))

<b>MOT #7</b>	2022-03-02 09:01
MOT test number	302248342718
Result	✓ Passed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

<b>MOT #6</b>	2021-02-22 17:00
MOT test number	656678193762
Result	✓ Passed
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #5 2021-02-16 12:16

MOT test number 251459947930

Result ✗ Failed

**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2020-02-27 09:41

MOT test number 313478434724

Result ✓ Passed

MOT #3 2019-02-26 15:45

MOT test number 886915343560

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #2 2019-02-26 15:45

MOT test number 873051448516

Result ✗ Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-03-01 10:46

MOT test number 961323401571

Result ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>VX15ULO</b>
Plate since	2015-05-29
Current registration	<b>VX15ULO</b>
Plate since	2015-05-29

More info >



**Finance check**

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	11
<b>First mileage registration</b>	2015-03-01
<b>Last registration</b>	2024-02-21
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2015-03-01	11 mi
<b>Registration #2</b>	2018-03-01	47.662 mi
<b>Registration #3</b>	2019-02-26	62.100 mi
<b>Registration #4</b>	2019-02-26	62.100 mi
<b>Registration #5</b>	2020-02-27	75.221 mi
<b>Registration #6</b>	2021-02-16	85.358 mi
<b>Registration #7</b>	2022-02-21	95.221 mi
<b>Registration #8</b>	2022-02-21	95.221 mi
<b>Registration #9</b>	2022-02-21	95.221 mi
<b>Registration #10</b>	2022-02-21	95.221 mi
<b>Registration #11</b>	2024-02-21	111.111 mi

[More info >](#)



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1175 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

G4LCEU324087