



General information

Make	VOLKSWAGEN
Model	POLO SEL TDI
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	230 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-21
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	13
Total items failed	9

MOT #16	2023-12-22 11:36
MOT test number	587962070923
Result	✓ Passed
Next expiry date	2024-12-21

MOT #15	2023-07-27 10:23
MOT test number	301054252077
Result	✓ Passed
Advice	Rear wiper blade split

MOT #14	2023-07-27 10:23
MOT test number	630284556443
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Rear wiper blade split

MOT #13	2022-08-04 10:49
MOT test number	998710050054
Result	✓ Passed

**MOT #12** 2021-08-06 12:01**MOT test number** 455701473198**Result** ✓ Passed**MOT #11** 2021-08-06 12:01**MOT test number** 374036012974**Result** ✗ Failed**Pass with rectification** Brake pad(s) less than 1.5 mm thick all around (1.1.13 (a) (ii))**Pass with rectification** Brake disc significantly and obviously worn all around (1.1.14 (a) (i))**MOT #10** 2020-06-18 09:18**MOT test number** 683940291181**Result** ✓ Passed**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both n/s and o/s (5.3.2 (b))**MOT #9** 2020-06-18 08:37**MOT test number** 334235377801**Result** ✗ Failed**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both n/s and o/s (5.3.2 (b))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-06-06 13:30**MOT test number** 213013707967**Result** ✓ Passed**Advice** Rear Seat belt flexible stalk damaged catch cover missing (7.1.2 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #7** 2019-06-06 13:30**MOT test number** 724110982277**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Seat belt flexible stalk damaged catch cover missing (7.1.2 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2018-06-21 10:13**MOT test number** 377020294619**Result** ✓ Passed**MOT #5** 2017-06-05 07:55**MOT test number** 202317151499**Result** ✓ Passed**MOT #4** 2017-06-02 08:47**MOT test number** 110087166682**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2016-06-30 09:08**MOT test number** 495101799780**Result** ✓ Passed



MOT #2	2015-07-02 12:58
MOT test number	489923685130
Result	✓ Passed
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #1	2015-07-02 10:27
MOT test number	986223985118
Result	✗ Failed
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Fail	Nearside Rear Brake hose twisted (3.6.B.4c)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 December 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	BL12HFS
Plate since	2024-03-29
Current registration	BL12HFS
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-07-04
Last registration	2023-12-22
Complete history	See info



Registration #1	2012-07-04	29 mi
Registration #2	2015-07-02	49.918 mi
Registration #3	2015-07-02	49.918 mi
Registration #4	2016-06-30	60.254 mi
Registration #5	2017-06-02	71.320 mi
Registration #6	2017-06-05	71.320 mi
Registration #7	2018-06-21	82.271 mi
Registration #8	2019-06-06	95.446 mi
Registration #9	2019-06-06	95.446 mi
Registration #10	2019-06-06	95.446 mi
Registration #11	2019-06-06	95.446 mi
Registration #12	2019-06-06	95.446 mi
Registration #13	2019-06-06	95.446 mi
Registration #14	2019-06-06	95.446 mi
Registration #15	2019-06-06	95.446 mi
Registration #16	2019-06-06	95.446 mi
Registration #17	2019-06-06	95.446 mi
Registration #18	2019-06-06	95.446 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1157 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Engine number

CAYBP30219