





report date: 2024-03-28

#### General information

Make	FIAT
Model	500C LOUNGE
Colour	Grey
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/13



WR15JHH

report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-08-15

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-27
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	22
Total items failed	9

MOT #10	2024-02-28 10:39
MOT test number	906462522978
Result	✓ Passed
Next expiry date	2025-02-27

MOT #9		2023-09-22 14:53
MOT test	number	256374724606
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/13



WR15JHH

report date: 2024-03-28

MOT #8 2023-09-22 11:30

**MOT test number** 546122239651

**Result** X Failed

**Fail** Windscreen wiper does not clear the windscreen effectively front wipers fouling each other (3.4 (b) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Nearside Rear Nail in tyre

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #7 2022-09-29 15:03

MOT test number 151457491032

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Advice** Oil leak, but not excessive sump (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

CarCheck.co.uk page 4/13



**Advice** 

WR15JHH

report date: 2024-03-28

**MOT #6** 2022-09-29 14:39 **MOT** test number 537997055895 Result × Failed **Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c)) **Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Fail Rear Registration plate does not conform to the specified requirements (0.1 (d)) Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) Fail Advice Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) **Advice Advice** Oil leak, but not excessive sump (8.4.1 (a) (i)) Fail Front Registration plate does not conform to the specified requirements (0.1 (d)) Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #5	2021-09-21 12:47
MOT test number	541751772410
Result	✓ Passed
MOT #4	2021-01-19 10:51
MOT test number	973808417100
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/13



MOT #3 2020-01-27 12:52

**MOT test number** 351279018857

**Result** ✓ Passed

MOT #2 2020-01-27 12:03

MOT test number 444403133354

Result X Failed

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1 2018-02-21 16:42

**MOT test number** 427205748029

**Result** 
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



#### Extra FIAT salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



WR15JHH

report date: 2024-03-28

Owner history	
---------------	--

Owner mistory		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		?
********		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK W	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-31
Last registration	2024-02-28
Complete history	See info



Registration #1	2015-03-31	15 mi
Registration #2	2018-02-21	24.353 mi
Registration #3	2020-01-27	52.435 mi
Registration #4	2020-01-27	52.439 mi
Registration #5	2021-01-19	61.847 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71,777 es

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/1.

Number of axles2Engine number1197677