



report date: 2024-03-29

General information

Make	MINI
Model	COOPER D
Colour	White
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-07-01
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	23
Total items failed	9

MOT #13	2023-06-19 09:26
MOT test number	757997310653
Result	✓ Passed
Next expiry date	2024-07-04
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2022-07-05 15:58
MOT test number	329241080454
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened axle (5.3.3 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #11**

2022-01-13 14:16

MOT test number

503075354118

Result

✓ Passed

Advice

Rear Sub-frame corroded but not seriously weakened axle (5.3.3 (b) (i))

Advice

Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

Advice

Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

2020-12-17 16:10

MOT test number

232587663590

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge inner edge 0-1mm (5.2.3 (e))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9

2019-12-12 10:29

MOT test number

154337839551

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8

2018-12-17 09:23

MOT test number

724904376794

Result

✓ Passed

**MOT #7** 2017-12-18 14:47**MOT test number** 201922547570**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-12-18 12:39**MOT test number** 654940116271**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-12-15 13:06**MOT test number** 843892391041**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2016-12-15 11:49**MOT test number** 216025711221**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2015-12-14 12:50**MOT test number** 718208664385**Result** ✓ Passed**MOT #2** 2015-12-14 12:50**MOT test number** 738919001682**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2014-12-18 08:52**MOT test number** 448292654316**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-02-25
Last registration	2023-06-19
Complete history	See info



Registration #1	2012-02-25	15 mi
Registration #2	2014-12-18	40.347 mi
Registration #3	2015-12-14	51.256 mi
Registration #4	2015-12-14	51.256 mi
Registration #5	2016-12-15	69.063 mi
Registration #6	2016-12-15	69.063 mi
Registration #7	2017-12-18	86.761 mi
Registration #8	2017-12-18	86.761 mi
Registration #9	2018-06-20	86.761 mi
Registration #10	2018-06-20	86.761 mi
Registration #11	2018-06-20	86.761 mi
Registration #12	2018-06-20	86.761 mi
Registration #13	2018-06-20	86.761 mi
Registration #14	2018-06-20	86.761 mi
Registration #15	2018-06-20	86.761 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	70398036