





General information

| Make | AUDI |
|---------------------|----------------|
| Model | A4 RS4 QUATTRO |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 155 mph |
| 0 - 60 mph | 4.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption


| Power | 420 BHP |
|-------------------------|---------------------|
| Max. torque | 429 Nm at 5.500 rpm |
| Cylinders | 8 |
| Fuel type | Petrol |
| Consumption city | 13.6 mpg |
| Consumption extra urban | 30.1 mpg |
| Consumption combined | 20.9 mpg |





Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-05-23 |
| Pictures | 10 |
| Listing price | View report |









source: autotrader.co.uk



MOT history

| MOT #12 | 2022-03-16 09:50 |
|------------------|------------------|
| MOT test number | 952565254827 |
| Result | ✓ Passed |
| Next expiry date | 2023-03-15 |

| MOT #11 | 2020-11-06 11:18 |
|----------|--|
| MOT test | number 306387433498 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Suspension pipes slightly corroded |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| MOT #10 | 2019-06-06 21:13 |
|----------|--|
| MOT test | number 914296430668 |
| Result | ✓ Passed |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |





| MOT #9 | 2019-05-03 21:24 |
|---|------------------|
| MOT test number | 938019189967 |
| Result | 🗙 Failed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Front Service brake excessively binding (1.2.1 (f)) | |
| Advice Offside Front Shock absorbers light misting of oil or has limited damping effect | t (5.3.2 (b)) |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Service brake efficiency below requirements (1.2.2 (a) (i)) | |

| MOT #8 | 2018-02-16 12:58 |
|-----------------|------------------|
| MOT test number | 733322471062 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2017-02-20 14:41 |
| MOT test number | 915529234785 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2016-02-04 11:49 |
| | 574060610000 |

| MOT test number | 574269612329 |
|-----------------|--------------|
| Result | ✓ Passed |





| MOT #5 | 2015-01-23 17:49 |
|-----------------|------------------|
| MOT test number | 958283225099 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2014-02-03 09:37 |
| MOT test number | 277834334018 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2012-07-18 16:44 |
| MOT test number | 256980602213 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2011-08-09 09:12 |
| MOT test number | 616001221249 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2010-05-21 10:01 |
| MOT test number | 210441440477 |
| Result | ✓ Passed |





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2007-05-11 |
| Last registration | 2022-03-16 |
| Complete history | See info |



| Registration #1 | 2007-05-11 | 19 mi |
|---|------------|--|
| Registration #2 | 2010-05-21 | 22.901 mi |
| Registration #3 | 2011-08-09 | 26.445 mi |
| Registration #4 | 2012-07-18 | 28.704 mi |
| Registration #5 | 2014-02-03 | 30.123 mi |
| Registration #6 | 2015-01-23 | 36.010 mi |
| Registration #7 | 2016-02-04 | 42.069 mi |
| | | |
| Registration #8 | | 11.777 est |
| Registration #8 Registration #9 | | 11.777 es |
| | | 11.227 es |
| Registration #9 | | 11.227 es 11.227 es 11.227 es 11.227 es |
| Registration #9 Registration #10 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #9 Registration #10 Registration #11 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1816 mm |
| Height | 1415 mm |
| Length | 4589 mm |
| Wheel base | 2651 mm |
| Kerb weight | 1650 kg |
| Max. allowed weight | 2200 kg |
| Additional information | |
| Fuel tank capacity | 63 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | BNS 013301 |